

# **Desktop 4th Generation Intel<sup>®</sup> Core<sup>™</sup> Processor Family, Desktop Intel<sup>®</sup> Pentium<sup>®</sup> Processor Family, and Desktop Intel<sup>®</sup> Celeron<sup>®</sup> Processor Family**

**Specification Update**

---

*June 2014*

*Revision 013*



By using this document, in addition to any agreements you have with Intel, you accept the terms set forth below.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or go to: <http://www.intel.com/design/literature.htm>.

Code names featured are used internally within Intel to identify products that are in development and not yet publicly announced for release. Customers, licensees and other third parties are not authorized by Intel to use code names in advertising, promotion or marketing of any product or services and any such use of Intel's internal code names is at the sole risk of the user.

Intel® Virtualization Technology requires a computer system with an enabled Intel® processor, BIOS, virtual machine monitor (VMM). Functionality, performance or other benefits will vary depending on hardware and software configurations. Software applications may not be compatible with all operating systems. Consult your PC manufacturer. For more information, visit: <http://www.intel.com/go/virtualization>.

Intel® Turbo Boost Technology requires a system with Intel® Turbo Boost Technology. Intel Turbo Boost Technology and Intel Turbo Boost Technology 2.0 are only available on select Intel® processors. Consult your PC manufacturer. Performance varies depending on hardware, software, and system configuration. For more information, visit: <http://www.intel.com/go/turbo>.

Intel® Hyper-Threading Technology requires an Intel® HT Technology enabled system, check with your PC manufacturer. Performance will vary depending on the specific hardware and software used. Not available on Intel® Core™ i5-750. For more information including details on which processors support HT Technology, visit <http://www.intel.com/info/hyperthreading>.

Intel® 64 architecture requires a system with a 64-bit enabled processor, chipset, BIOS and software. Performance will vary depending on the specific hardware and software you use. Consult your PC manufacturer for more information. For more information, visit: <http://www.intel.com/info/em64t>.

Intel, Intel Core, Intel386, Intel486, Pentium, and the Intel logo are trademarks of Intel Corporation in the U.S. and other countries.

\*Other names and brands may be claimed as the property of others.

Copyright © 2013–2014, Intel Corporation. All rights reserved.




## Contents

---

Revision History .....	5
Preface .....	6
Summary Tables of Changes .....	8
Identification Information .....	14
Errata .....	18
Specification Changes .....	50
Specification Clarifications .....	51
Documentation Changes .....	52

§ §





# Revision History

Revision	Description	Date
001	<ul style="list-style-type: none"><li>Initial Release.</li></ul>	June 2013
002	<ul style="list-style-type: none"><li>No Updates. Revision number added to Revision History to maintain consistency with NDA Specification Update numbering.</li></ul>	N/A
003	<ul style="list-style-type: none"><li>Errata<ul style="list-style-type: none"><li>Added HSD59-99</li></ul></li><li>Updated Identification Information</li></ul>	August 2013
004	<ul style="list-style-type: none"><li>No Updates. Revision number added to Revision History to maintain consistency with NDA Specification Update numbering.</li></ul>	N/A
005	<ul style="list-style-type: none"><li>Errata<ul style="list-style-type: none"><li>Moved previous HSD99 to HSD108</li><li>Added HSD99-107 and HSD109-115</li></ul></li><li>Updated Identification Information</li></ul>	November 2013
006	<ul style="list-style-type: none"><li>Identification Information<ul style="list-style-type: none"><li>Updated Desktop Processor Identification table</li></ul></li></ul>	December 2013
007	<ul style="list-style-type: none"><li>Errata<ul style="list-style-type: none"><li>Added HSD116-118</li></ul></li></ul>	December 2013
008	<ul style="list-style-type: none"><li>Errata<ul style="list-style-type: none"><li>Added HSD119-121</li></ul></li><li>Updated Table 2, "Desktop Processor Identification"</li></ul>	January 2014
009	<ul style="list-style-type: none"><li>Errata<ul style="list-style-type: none"><li>Added HSD122-123</li></ul></li><li>Updated Desktop Processor Identification by Register Contents table</li></ul>	February 2014
010	<ul style="list-style-type: none"><li>Added the phrase "4th Generation Intel® Core™ processor based on Desktop R-Processor SKUs (BGA) with GT3 Graphics"</li><li>Errata<ul style="list-style-type: none"><li>Modified HSD29</li><li>Added HSD124</li></ul></li><li>Updated Table 3, Processor Identification by Register Contents</li></ul>	March 2014
011	<ul style="list-style-type: none"><li>Added the phrase "4th Generation Intel® Core™ processor based on Desktop R-Processor SKUs (BGA) with GT3 Graphics"</li><li>Errata<ul style="list-style-type: none"><li>Added HSD125-128</li></ul></li><li>Processor Identification<ul style="list-style-type: none"><li>Updated Table 2, Processor Identification by Register Contents</li></ul></li></ul>	April 2014
012	<ul style="list-style-type: none"><li>Processor Identification<ul style="list-style-type: none"><li>Updated Table 2, Processor Identification by Register Contents</li></ul></li></ul>	May 2014
013	<ul style="list-style-type: none"><li>Processor Identification<ul style="list-style-type: none"><li>Updated Table 3, Desktop Processor Identification</li></ul></li></ul>	June 2014



## Preface

This document is an update to the specifications contained in the [Affected Documents](#) table below. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in [Nomenclature](#) are consolidated into the specification update and are no longer published in other documents.


This document may also contain information that was not previously published.

### Affected Documents

Document Title	Document Number
<i>Desktop 4th Generation Intel® Core™ Processor Family, Desktop Intel® Pentium® Processor Family, and Desktop Intel® Celeron® Processor Family Datasheet – Volume 1 of 2</i>	328897
<i>Desktop 4th Generation Intel® Core™ Processor Family, Desktop Intel® Pentium® Processor Family, and Desktop Intel® Celeron® Processor Family Datasheet – Volume 2 of 2</i>	328898

### Related Documents

Document Title	Document Number/ Location
<i>AP-485, Intel® Processor Identification and the CPUID Instruction</i>	<a href="http://www.intel.com/design/processor/applnots/241618.htm">http://www.intel.com/design/processor/applnots/241618.htm</a>
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 1: Basic Architecture</i> <i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2A: Instruction Set Reference Manual A-M</i> <i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2B: Instruction Set Reference Manual N-Z</i> <i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide</i> <i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3B: System Programming Guide</i> <i>Intel® 64 and IA-32 Intel Architecture Optimization Reference Manual</i>	<a href="http://www.intel.com/products/processor/manuals/index.htm">http://www.intel.com/products/processor/manuals/index.htm</a>
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual Documentation Changes</i>	<a href="http://www.intel.com/design/processor/specupdt/252046.htm">http://www.intel.com/design/processor/specupdt/252046.htm</a>
<i>ACPI Specifications</i>	<a href="http://www.acpi.info">www.acpi.info</a>



## Nomenclature

**Errata** are design defects or errors. These may cause the processor behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

**S-Spec Number** is a five-digit code used to identify products. Products are differentiated by their unique characteristics such as, core speed, L2 cache size, package type, etc. as described in the processor identification information table. Read all notes associated with each S-Spec number.

**Specification Changes** are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

**Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

**Documentation Changes** include typos, errors, or omissions from the current published specifications. These will be incorporated in any new release of the specification.

**Note:** Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, and so on).



# Summary Tables of Changes

---

The following tables indicate the errata, specification changes, specification clarifications, or documentation changes which apply to the processor. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. These tables use the following notations.

## Codes Used in Summary Tables

### Stepping

X:	Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.
(No mark) or (Blank box):	This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

### Page


(Page):	Page location of item in this document.
---------	---

### Status

Doc:	Document change or update will be implemented.
Plan Fix:	This erratum may be fixed in a future stepping of the product.
Fixed:	This erratum has been previously fixed.
No Fix:	There are no plans to fix this erratum.

### Row

Change bar to left of a table row indicates this erratum is either new or modified from the previous version of the document.



## Errata (Sheet 1 of 5)

Number	Steppings	Status	ERRATA
	C-0		
HSD1	X	No Fix	LBR, BTS, BTM May Report a Wrong Address when an Exception/Interrupt Occurs in 64-bit Mode
HSD2	X	No Fix	EFLAGS Discrepancy on Page Faults and on EPT-Induced VM Exits after a Translation Change
HSD3	X	No Fix	MCi_Status Overflow Bit May Be Incorrectly Set on a Single Instance of a DTLB Error
HSD4	X	No Fix	LER MSRs May Be Unreliable
HSD5	X	No Fix	MONITOR or CLFLUSH on the Local XAPIC's Address Space Results in Hang
HSD6	X	No Fix	An Uncorrectable Error Logged in IA32_CR_MC2_STATUS May also Result in a System Hang
HSD7	X	No Fix	#GP on Segment Selector Descriptor that Straddles Canonical Boundary May Not Provide Correct Exception Error Code
HSD8	X	No Fix	FREEZE_WHILE_SMM Does Not Prevent Event From Pending PEBS During SMM
HSD9	X	No Fix	APIC Error "Received Illegal Vector" May be Lost
HSD10	X	No Fix	Changing the Memory Type for an In-Use Page Translation May Lead to Memory-Ordering Violations
HSD11	X	No Fix	Performance Monitor Precise Instruction Retired Event May Present Wrong Indications
HSD12	X	No Fix	CR0.CD Is Ignored in VMX Operation
HSD13	X	No Fix	Instruction Fetch May Cause Machine Check if Page Size and Memory Type Was Changed Without Invalidation
HSD14	X	No Fix	Execution of VAESIMC or VAESKEYGENASSIST With An Illegal Value for VEX.vvvv May Produce a #NM Exception
HSD15	X	No Fix	Processor May Fail to Acknowledge a TLP Request
HSD16	X	No Fix	Interrupt From Local APIC Timer May Not Be Detectable While Being Delivered
HSD17	X	No Fix	PCIe* Root-port Initiated Compliance State Transmitter Equalization Settings May be Incorrect
HSD18	X	No Fix	PCIe* Controller May Incorrectly Log Errors on Transition to RxL0s
HSD19	X	No Fix	Unused PCIe* Lanes May Report Correctable Errors
HSD20	X	No Fix	Accessing Physical Memory Space 0-640K through the Graphics Aperture May Cause Unpredictable System Behavior
HSD21	X	No Fix	PCIe Root Port May Not Initiate Link Speed Change
HSD22	X	No Fix	Pending x87 FPU Exceptions (#MF) May be Signaled Earlier Than Expected
HSD23	X	No Fix	DR6.B0-B3 May Not Report All Breakpoints Matched When a MOV/POP SS is Followed by a Store or an MMX Instruction
HSD24	X	No Fix	VEX.L is Not Ignored with VCVT*2SI Instructions
HSD25	X	No Fix	Certain Local Memory Read / Load Retired PerfMon Events May Undercount
HSD26	X	No Fix	Specific Graphics Blitter Instructions May Result in Unpredictable Graphics Controller Behavior
HSD27	X	No Fix	Processor May Enter Shutdown Unexpectedly on a Second Uncorrectable Error
HSD28	X	No Fix	Modified Compliance Patterns for 2.5 GT/s and 5 GT/s Transfer Rates Do Not Follow PCIe* Specification
HSD29	X	No Fix	Performance Monitor Counters May Produce Incorrect Results



## Errata (Sheet 2 of 5)

Number	Steppings	Status	ERRATA
	C-0		
HSD30	X	No Fix	Performance Monitor UOPS_EXECUTED Event May Undercount
HSD31	X	No Fix	MSR_PERF_STATUS May Report an Incorrect Core Voltage
HSD32	X	No Fix	PCIe* Atomic Transactions From Two or More PCIe Controllers May Cause Starvation
HSD33	X	No Fix	The Corrected Error Count Overflow Bit in IA32_MC0_STATUS is Not Updated After a UC Error is Logged
HSD34	X	No Fix	An AVX Gather Instruction That Causes an EPT Violation May Not Update Previous Elements
HSD35	X	No Fix	PLATFORM_POWER_LIMIT MSR Not Visible
HSD36	X	No Fix	LPDDR Memory May Report Incorrect Temperature
HSD37	X	No Fix	PCIe* Host Bridge DID May Be Incorrect
HSD38	X	No Fix	TSC May be Incorrect After a Deep C-State Exit
HSD39	X	No Fix	PCIe* Controller May Initiate Speed Change While in DL_Init State Causing Certain PCIe Devices to Fail to Train
HSD40	X	No Fix	Spurious VT-d Interrupts May Occur When the PFO Bit is Set
HSD41	X	No Fix	N/A. Erratum has been removed.
HSD42	X	No Fix	AVX Gather Instruction That Causes a Fault or VM Exit May Incorrectly Modify Its Destination Register
HSD43	X	No Fix	Inconsistent NaN Propagation May Occur When Executing (V)DPSS Instruction
HSD44	X	No Fix	Display May Flicker When Package C-States Are Enabled
HSD45	X	No Fix	Certain Combinations of AVX Instructions May Cause Unpredictable System Behavior
HSD46	X	No Fix	Processor May Incorrectly Estimate Peak Power Delivery Requirements
HSD47	X	No Fix	IA32_PERF_CTL MSR is Incorrectly Reset
HSD48	X	No Fix	Processor May Hang During a Function Level Reset of the Display
HSD49	X	No Fix	AVX Gather Instruction That Should Result in #DF May Cause Unexpected System Behavior
HSD50	X	No Fix	Throttling and Refresh Rate Maybe be Incorrect After Exiting Package C-State
HSD51	X	No Fix	Processor May Livelock During On Demand Clock Modulation
HSD52	X	No Fix	IA32_DEBUGCTL.FREEZE_PERFMON_ON_PMI is Incorrectly Cleared by SMI
HSD53	X	No Fix	The From-IP for Branch Tracing May be Incorrect
HSD54	X	No Fix	TM1 Throttling May Continue indefinitely
HSD55	X	No Fix	Internal Parity Errors May Incorrectly Report Overflow in The IA32_MCI_STATUS MSR
HSD56	X	No Fix	Performance Monitor Events OTHER_ASSISTS.AVX_TO_SSE And OTHER_ASSISTS.SSE_TO_AVX May Over Count
HSD57	X	No Fix	Processor May Run at Incorrect P-State
HSD58	X	No Fix	Performance Monitor Event DSB2MITE_SWITCHES.COUNT May Over Count
HSD59	X	No Fix	Performance Monitor Register UNC_PERF_GLOBAL_STATUS Not Restored on Package C7 Exit
HSD60	X	No Fix	Processor May Not Enter Package C6 or Deeper C-states When PCIe* Links Are Disabled




## Errata (Sheet 3 of 5)

Number	Steppings	Status	ERRATA
	C-0		
HSD61	X	No Fix	Performance Monitor Event For Outstanding Offcore Requests And Snoop Requests May Over Count
HSD62	X	No Fix	Some Performance Monitor Event Counts May be Inaccurate During SMT Mode
HSD63	X	No Fix	Timed MWAIT May Use Deadline of a Previous Execution
HSD64	X	No Fix	The Upper 32 Bits of CR3 May be Incorrectly Used With 32-Bit Paging
HSD65	X	No Fix	Performance Monitor Events HLE_RETIRED.ABORTED_MISC4 And RTM_RETIRED.ABORTED_MISC4 May Over Count
HSD66	X	No Fix	A PCIe* LTR Update Message May Cause The Processor to Hang
HSD67	X	No Fix	GETSEC Does Not Report Support For S-CRTM
HSD68	X	No Fix	EPT Violations May Report Bits 11:0 of Guest Linear Address Incorrectly
HSD69	X	No Fix	APIC Timer Might Not Signal an Interrupt While in TSC-Deadline Mode
HSD70	X	No Fix	IA32_VMX_VMCS_ENUM MSR (48AH) Does Not Properly Report The Highest Index Value Used For VMCS Encoding
HSD71	X	No Fix	Incorrect FROM_IP Value For an RTM Abort in BTM or BTS May be Observed
HSD72	X	No Fix	VT-d Hardware May Perform STRP And SIRTTP Operations on a Package C7 Exit
HSD73	X	No Fix	General-Purpose Performance Counters Can Unexpectedly Increment
HSD74	X	No Fix	Performance Monitoring Events May Report Incorrect Number of Load Hits or Misses to LLC
HSD75	X	No Fix	Performance Monitoring Event INSTR_RETIRED.ALL May Generate Redundant PEBS Records For an Overflow
HSD76	X	No Fix	Locked Load Performance Monitoring Events May Under Count
HSD77	X	No Fix	Graphics Processor Ratio And C-State Transitions May Cause a System Hang
HSD78	X	No Fix	Certain Performance Monitoring Events May Over Count Software Demand Loads
HSD79	X	No Fix	Accessing Nonexistent Uncore Performance Monitoring MSRs May Not Signal a #GP
HSD80	X	No Fix	Call Stack Profiling May Produce Extra Call Records
HSD81	X	No Fix	Warm Reset May Fail or Lead to Incorrect Power Regulation
HSD82	X	No Fix	PCIe* Host Bridge DID May Be Incorrect
HSD83	X	No Fix	Transactional Abort May Produce an Incorrect Branch Record
HSD84	X	No Fix	SMRAM State-Save Area Above the 4GB Boundary May Cause Unpredictable System Behavior
HSD85	X	No Fix	DMA Remapping Faults for the Graphics VT-d Unit May Not Properly Report Type of Faulted Request
HSD86	X	No Fix	AVX Gather Instructions Page Faults May Report an Incorrect Faulting Address
HSD87	X	No Fix	Intel® TSX Instructions May Cause Unpredictable System behavior
HSD88	X	No Fix	Event Injection by VM Entry May Use an Incorrect B Flag for SS
HSD89	X	No Fix	A Fault in SMM May Result in Unpredictable System Behavior
HSD90	X	No Fix	Processor Frequency is Unexpectedly Limited Below Nominal P1 When CTDP Down is Enabled
HSD91	X	No Fix	PMI May be Signaled More Than Once For Performance Monitor Counter Overflow



## Errata (Sheet 4 of 5)

Number	Steppings	Status	ERRATA
	C-0		
HSD92	X	No Fix	Execution of FXSAVE or FXRSTOR With the VEX Prefix May Produce a #NM Exception
HSD93	X	No Fix	RDRAND Execution in a Transactional Region May Cause a System Hang
HSD94	X	No Fix	Uncore Clock Frequency Changes May Cause Audio/Video Glitches
HSD95	X	No Fix	Processor May Experience a Spurious LLC-Related Machine Check During Periods of High Activity
HSD96	X	No Fix	The Processor May Not Enter Package C7 When Using a PSR Display
HSD97	X	No Fix	Video/Audio Distortion May Occur
HSD98	X	No Fix	System May Hang When Audio is Enabled During Package C3
HSD99	X	No Fix	INVPCID May Not Cause #UD in VMX Non-Root Operation
HSD100	X	No Fix	Non-Compliant PFAT Module Base Address May Cause Unpredictable System Behavior
HSD101	X	No Fix	Incorrect LBR Source Address May be Reported For a Transactional Abort
HSD102	X	No Fix	Address Translation Faults for Intel® VT-d May Not be Reported for Display Engine Memory Accesses
HSD103	X	No Fix	L3 Cache Corrected Error Count May be Inaccurate After Package C7 Exit
HSD104	X	No Fix	PCIe* Device's SVID is Not Preserved Across The Package C7 C-State
HSD105	X	No Fix	Warm Reset Does Not Stop GT Power Draw
HSD106	X	No Fix	Unused PCIe* Lanes May Remain Powered After Package C7
HSD107	X	No Fix	BMI1 And BMI2 Instruction Groups Are Not Available
HSD108	X	No Fix	Virtual-APIC Page Accesses With 32-Bit PAE Paging May Cause a System Crash
HSD109	X	No Fix	Processor Energy Policy Selection May Not Work as Expected
HSD110	X	No Fix	A PEBS Record May Contain Processor State for an Unexpected Instruction
HSD111	X	No Fix	MSR_PP1_ENERGY_STATUS Reports Incorrect Energy Data
HSD112	X	No Fix	x87 FPU DP May be Incorrect After Instructions That Save FP State to Memory
HSD113	X	No Fix	Processor May Hang During Package C7 Exit
HSD114	X	No Fix	Intel® TSX Instructions May Cause Unpredictable System behavior
HSD115	X	No Fix	Spurious LLC Machine Check May Occur
HSD116	X	No Fix	Page Fault May Report Incorrect Fault Information
HSD117	X	No Fix	CATERR# Pin Assertion is Not Cleared on a Warm Reset
HSD118	X	No Fix	Uncorrectable Machine Check Error During Core C6 Entry May Not be Signaled
HSD119	X	No Fix	The SAMPLE/PRELOAD JTAG Command Does Not Sample The Display Transmit Signals
HSD120	X	No Fix	Performance Monitor Event For Outstanding Offcore Requests And Snoop Requests May be Incorrect
HSD121	X	No Fix	Processor Energy Policy Selection May Not Work as Expected
HSD122	X	No Fix	PCIe Link May Incorrectly Train to 8.0 GT/s
HSD123	X	No Fix	PCIe Tx Voltage Reference Cannot be Changed
HSD124	X	No Fix	VM Exit May Set IA32_EFER.NXE When IA32_MISC_ENABLE Bit 34 is Set to 1



## Errata (Sheet 5 of 5)

Number	Steppings	Status	ERRATA
	C-0		
HSD125 <sup>1</sup>	X	No Fix	Re-enabling eDRAM May Log a Machine Check and Hang
HSD126 <sup>1</sup>	X	No Fix	Warm Reset Does Not Stop EDRAM Power Draw
HSD127	X	No Fix	Opcode Bytes F3 0F BC May Execute As TZCNT Even When TZCNT Not Enumerated by CPUID
HSD128	X	No Fix	Intel® S2DDT May Not Function Correctly with Certain High Resolution Displays

**Note:**

1. 4th Generation Intel® Core™ processor based on Desktop R-Processor SKUs (BGA) with GT3 Graphics Only

## Specification Changes

Number	SPECIFICATION CHANGES
	None for this revision of this specification update.

## Specification Clarifications

Number	SPECIFICATION CLARIFICATIONS
	None for this revision of this specification update.

## Documentation Changes

Number	DOCUMENTATION CHANGES
HSD1	"On-Demand Clock Modulation Feature Clarification"



# Identification Information

## Component Identification using Programming Interface

The processor stepping can be identified by the following register contents.

**Table 1. Desktop 4th Generation Intel® Core™ Processor Family Component Identification**

Reserved	Extended Family	Extended Model	Reserved	Processor Type	Family Code	Model Number	Stepping ID
31:28	27:20	19:16	15:14	13:12	11:8	7:4	3:0
	00000000b	0011b		00b	0110b	1100b	xxxxb

**Notes:**

1. The Extended Family, Bits [27:20] are used in conjunction with the Family Code, specified in Bits [11:8], to indicate whether the processor belongs to the Intel386™, Intel486™, Pentium®, Pentium 4, or Intel® Core™ processor family.
2. The Extended Model, Bits [19:16] in conjunction with the Model Number, specified in Bits [7:4], are used to identify the model of the processor within the processor's family.
3. The Family Code corresponds to Bits [11:8] of the EDX register after RESET, Bits [11:8] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the generation field of the Device ID register accessible through Boundary Scan.
4. The Model Number corresponds to Bits [7:4] of the EDX register after RESET, Bits [7:4] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the model field of the Device ID register accessible through Boundary Scan.
5. The Stepping ID in Bits [3:0] indicates the revision number of that model. See the processor Identification table for the processor stepping ID number in the CPUID information.

When EAX is initialized to a value of `1`, the CPUID instruction returns the Extended Family, Extended Model, Processor Type, Family Code, Model Number and Stepping ID value in the EAX register. Note that the EDX processor signature value after reset is equivalent to the processor signature output value in the EAX register.

Cache and TLB descriptor parameters are provided in the EAX, EBX, ECX and EDX registers after the CPUID instruction is executed with a 2 in the EAX register.

The processor can be identified by the following register contents.

**Table 2. Processor Identification by Register Contents**

Processor Line	Stepping	Vendor ID <sup>1</sup>	Host Device ID <sup>2</sup>	Processor Graphics Device ID <sup>3</sup>	Revision ID <sup>4</sup>	CRID
4th Generation Intel® Core™ processor Series (with GT3 Graphics)	C-0	8086h	0D00h	GT3 = 0D22h	08h	08h
4th Generation Intel® Core™ processor Series (Traditional)	C-0	8086h	0C00h	GT1 = 0402h GT2 = 0412h	06h	06h


**Notes:**

1. The Vendor ID corresponds to bits 15:0 of the Vendor ID Register located at offset 00h–01h in the PCI function 0 configuration space.
2. The Host Device ID corresponds to bits 15:0 of the Device ID Register located at Device 0 offset 02h–03h in the PCI function 0 configuration space.
3. The Processor Graphics Device ID (DID2) corresponds to bits 15:0 of the Device ID Register located at Device 2 offset 02h–03h in the PCI function 0 configuration space.
4. The Revision Number corresponds to bits 7:0 of the Revision ID Register located at offset 08h in the PCI function 0 configuration space.

## Component Marking Information

The processor stepping can be identified by the following component markings.

**Figure 1. Desktop 4th Generation Intel® Core™ Processor Family Top-Side Markings**



**Sample (QDF)**  
GRP1LINE1: i{M}{C}YY  
GRP1LINE2: INTEL CONFIDENTIAL  
GRP1LINE3: QDF ES SPEED  
GRP1LINE4: XXXXX  
GRP1LINE5: {FPO} {e4}

**Production (SSPEC)**  
GRP1LINE1: i{M}{C}YY  
GRP1LINE2: SUB-BRAND PROC#  
GRP1LINE3: SSPEC SPEED  
GRP1LINE4: XXXXX  
GRP1LINE5: {FPO} {e4}

**FOL Mark:**  
2D Matrix and Human Readable  
Serial# (4 characters)

XXXXX = Country of Origin

Pkg Size = 37.5mm x 37.5mm  
Pin Count = 1150

**Table 3. Desktop Processor Identification (Sheet 1 of 3)**

S-Spec Number	Processor Number	Stepping	Cache Size (MB)	Functional Core	Integrated Graphics Cores	Max Turbo Freq. Rate (GHz)	Memory (MHz)	Core Freq. (GHz)	Thermal Design Power (W)
SR147	I7-4770K	C-0	8	4	2	3.9	1600	3.5	95
SR149	I7-4770	C-0	8	4	2	3.9	1600	3.4	95
SR14A	I5-4670K	C-0	6	4	2	3.8	1600	3.4	95
SR14D	I5-4670	C-0	6	4	2	3.8	1600	3.4	95
SR14E	I5-4570	C-0	6	4	2	3.6	1600	3.2	95
SR14F	I5-4440	C-0	6	4	2	3.3	1600	3.1	95
SR14G	I5-4430	C-0	6	4	2	3.2	1600	3	95
SR14H	I7-4770S	C-0	8	4	2	3.9	1600	3.1	65
SR14J	I5-4570S	C-0	6	4	2	3.6	1600	2.9	65
SR14K	I5-4670S	C-0	6	4	2	3.8	1600	3.1	65
SR14L	I5-4440S	C-0	6	4	2	3.3	1600	2.8	65
SR14M	I5-4430S	C-0	6	4	2	3.2	1600	2.7	65
SR14N	I7-4770T	C-0	8	4	2	3.7	1600	2.5	45
SR14P	I5-4670T	C-0	6	4	2	3.3	1600	2.3	45
SR14Q	I7-4765T	C-0	8	4	2	3	1600	2	35




**Table 3. Desktop Processor Identification (Sheet 2 of 3)**

S-Spec Number	Processor Number	Stepping	Cache Size (MB)	Functional Core	Integrated Graphics Cores	Max Turbo Freq. Rate (GHz)	Memory (MHz)	Core Freq. (GHz)	Thermal Design Power (W)
SR18K	I7-4770R	C-0	6	4	3	3.9	1600	3.2	65
SR18M	I5-4670R	C-0	4	4	3	3.7	1600	3	65
SR18Q	I5-4570R	C-0	4	4	3	3.2	1600	2.7	65
SR1BW	I7-4771	C-0	8	4	2	3.9	1600	3.5	95
SR1CA	I5-4570T	C-0	4	2	2	3.6	1600	2.9	35
SR17Z	i5-4570TE	C-0	4	2	2	3.3	1600	2.7	35
SR1CE	Pentium G3430	C-0	3	2	1	3.3	1600	3.3	65
SR1CG	Pentium G3220	C-0	3	2	1	3	1333	3	65
SR1CL	Pentium G3220T	C-0	3	2	1	2.6	1333	2.6	35
SR1NB	Pentium G3420	C-0	3	2	1	3.2	1333	3.2	65
SR1NK	I3-4330T	C-0	4	2	2	3	1600	3	35
SR1NL	I3-4340	C-0	4	2	2	3.6	1600	3.6	65
SR1NM	I3-4330	C-0	4	2	2	3.5	1600	3.5	65
SR1NN	I3-4130T	C-0	3	2	2	2.9	1600	2.9	35
SR1NP	I3-4130	C-0	3	2	2	3.4	1600	3.4	65
SR1CN	Celeron G1820	C-0	2	2	1	2.7	1333	2.7	65
SR1CP	Celeron G1820T	C-0	2	2	1	2.4	1333	2.4	35
SR1NC	Celeron G1830	C-0	2	2	1	2.8	1333	2.8	65
SR1KG	Celeron G1840	C-0	2	2	1	2.8	1333	2.8	65
SR1VK	Celeron G1840	C-0	2	2	1	2.8	1333	2.8	65
SR1KA	Celeron G1840T	C-0	2	2	1	2.5	1333	2.5	35
SR1KH	Celeron G1850	C-0	2	2	1	2.9	1333	2.9	65
SR1K6	Pentium G3240	C-0	3	2	1	3.1	1333	3.1	65
SR1RL	Pentium G3240	C-0	3	2	1	3.1	1333	3.1	65
SR1KU	Pentium G3240T	C-0	3	2	1	2.7	1333	2.7	35
SR1K5	Pentium G3440	C-0	3	2	1	3.3	1333	3.3	65
SR1P9	Pentium G3440	C-0	3	2	1	3.3	1600	3.3	65



**Table 3. Desktop Processor Identification (Sheet 3 of 3)**

S-Spec Number	Processor Number	Stepping	Cache Size (MB)	Functional Core	Integrated Graphics Cores	Max Turbo Freq. Rate (GHz)	Memory (MHz)	Core Freq. (GHz)	Thermal Design Power (W)
SR1KS	Pentium G3440T	C-0	3	2	1	2.8	1600	2.8	35
SR1K2	Pentium G3450	C-0	3	2	1	3.4	1600	3.4	65
SR1KP	I3-4150	C-0	3	2	2	3.5	1600	3.5	65
SR1PJ	I3-4150	C-0	3	2	2	3.5	1600	3.5	65
SR1KM	I3-4150T	C-0	3	2	2	3	1600	3	35
SR1PG	I3-4150T	C-0	3	2	2	3	1600	3	35
SR1K1	I3-4350	C-0	4	2	2	3.6	1600	3.6	65
SR1PF	I3-4350	C-0	4	2	2	3.6	1600	3.6	65
SR1JU	I3-4350T	C-0	4	2	2	3.1	1600	3.1	35
SR1PA	I3-4350T	C-0	4	2	2	3.1	1600	3.1	35
SR1JY	I3-4360	C-0	4	2	2	3.7	1600	3.7	65
SR1PC	I3-4360	C-0	4	2	2	3.7	1600	3.7	65
SR1QK	I5-4460	C-0	6	4	2	3.4	1600	3.2	95
SR1QQ	I5-4460S	C-0	6	4	2	3.4	1600	2.9	65
SR1S7	I5-4460T	C-0	6	4	2	2.7	1600	1.9	35
SR1QJ	I5-4590	C-0	6	4	2	3.7	1600	3.3	95
SR1QN	I5-4590S	C-0	6	4	2	3.7	1600	3	65
SR1H3	I5-4590T	C-0	4	2	2	3.8	1600	3.1	35
SR1QV	I5-4590T	C-0	4	2	2	3.8	1600	3.1	35
SR1S6	I5-4590T	C-0	6	4	2	3	1600	2	35
SR1QH	I5-4690	C-0	6	4	2	3.9	1600	3.5	95
SR1QP	I5-4690S	C-0	6	4	2	3.9	1600	3.2	65
SR1QT	I5-4690T	C-0	6	4	2	3.5	1600	2.5	45
SR1QU	I7-4785T	C-0	8	4	2	3.2	1600	2.2	35
SR1QF	I7-4790	C-0	8	4	2	4	1600	3.6	95
SR1QM	I7-4790S	C-0	8	4	2	4	1600	3.2	65
SR1QS	I7-4790T	C-0	8	4	2	3.9	1600	2.7	45
SR1V0	Pentium G3258	C-0	3	2	1	3.2	1333	3.2	65
SR1QE	I7-4790K	C-0	8	4	2	4.1	1600	3.7	95
SR1QG	I5-4690K	C-0	6	4	2	3.9	1600	3.5	95



# Errata

---

## **HSD1. LBR, BTS, BTM May Report a Wrong Address when an Exception/Interrupt Occurs in 64-bit Mode**

**Problem:** An exception/interrupt event should be transparent to the LBR (Last Branch Record), BTS (Branch Trace Store) and BTM (Branch Trace Message) mechanisms. However, during a specific boundary condition where the exception/interrupt occurs right after the execution of an instruction at the lower canonical boundary (0x00007FFFFFFFFF) in 64-bit mode, the LBR return registers will save a wrong return address with bits 63 to 48 incorrectly sign extended to all 1's. Subsequent BTS and BTM operations which report the LBR will also be incorrect.

**Implication:** LBR, BTS and BTM may report incorrect information in the event of an exception/interrupt.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

## **HSD2. EFLAGS Discrepancy on Page Faults and on EPT-Induced VM Exits after a Translation Change**

**Problem:** This erratum is regarding the case where paging structures are modified to change a linear address from writable to non-writable without software performing an appropriate TLB invalidation. When a subsequent access to that address by a specific instruction (ADD, AND, BTC, BTR, BTS, CMPXCHG, DEC, INC, NEG, NOT, OR, ROL/ROR, SAL/SAR/SHL/SHR, SHLD, SHRD, SUB, XOR, and XADD) causes a page fault or an EPT-induced VM exit, the value saved for EFLAGS may incorrectly contain the arithmetic flag values that the EFLAGS register would have held had the instruction completed without fault or VM exit. For page faults, this can occur even if the fault causes a VM exit or if its delivery causes a nested fault.

**Implication:** None identified. Although the EFLAGS value saved by an affected event (a page fault or an EPT-induced VM exit) may contain incorrect arithmetic flag values, Intel has not identified software that is affected by this erratum. This erratum will have no further effects once the original instruction is restarted because the instruction will produce the same results as if it had initially completed without fault or VM exit.

**Workaround:** If the handler of the affected events inspects the arithmetic portion of the saved EFLAGS value, then system software should perform a synchronized paging structure modification and TLB invalidation.

**Status:** For the steppings affected, see the *Summary Table of Changes*.


## **HSD3. MCI\_Status Overflow Bit May Be Incorrectly Set on a Single Instance of a DTLB Error**

**Problem:** A single Data Translation Look Aside Buffer (DTLB) error can incorrectly set the Overflow (bit [62]) in the MCI\_Status register. A DTLB error is indicated by MCA error code (bits [15:0]) appearing as binary value, 000x 0000 0001 0100, in the MCI\_Status register.

**Implication:** Due to this erratum, the Overflow bit in the MCI\_Status register may not be an accurate indication of multiple occurrences of DTLB errors. There is no other impact to normal processor functionality.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



#### **HSD4. LER MSRs May Be Unreliable**

**Problem:** Due to certain internal processor events, updates to the LER (Last Exception Record) MSRs, MSR\_LER\_FROM\_LIP (1DDH) and MSR\_LER\_TO\_LIP (1DEH), may happen when no update was expected.

**Implication:** The values of the LER MSRs may be unreliable.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD5. MONITOR or CLFLUSH on the Local xAPIC's Address Space Results in Hang**

**Problem:** If the target linear address range for a MONITOR or CLFLUSH is mapped to the local xAPIC's address space, the processor will hang.

**Implication:** When this erratum occurs, the processor will hang. The local xAPIC's address space must be uncached. The MONITOR instruction only functions correctly if the specified linear address range is of the type write-back. CLFLUSH flushes data from the cache. Intel has not observed this erratum with any commercially available software.

**Workaround:** Do not execute MONITOR or CLFLUSH instructions on the local xAPIC address space.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD6. An Uncorrectable Error Logged in IA32\_CR\_MC2\_STATUS May also Result in a System Hang**

**Problem:** Uncorrectable errors logged in IA32\_CR\_MC2\_STATUS MSR (409H) may also result in a system hang causing an Internal Timer Error (MCACOD = 0x0400h) to be logged in another machine check bank (IA32\_MCi\_STATUS).

**Implication:** Uncorrectable errors logged in IA32\_CR\_MC2\_STATUS can further cause a system hang and an Internal Timer Error to be logged.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD7. #GP on Segment Selector Descriptor that Straddles Canonical Boundary May Not Provide Correct Exception Error Code**

**Problem:** During a #GP (General Protection Exception), the processor pushes an error code on to the exception handler's stack. If the segment selector descriptor straddles the canonical boundary, the error code pushed onto the stack may be incorrect.

**Implication:** An incorrect error code may be pushed onto the stack. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



#### **HSD8. FREEZE\_WHILE\_SMM Does Not Prevent Event From Pending PEBS During SMM**

**Problem:** In general, a PEBS record should be generated on the first count of the event after the counter has overflowed. However, IA32\_DEBUGCTL\_MSR.FREEZE\_WHILE\_SMM (MSR 1D9H, bit [14]) prevents performance counters from counting during SMM (System Management Mode). Due to this erratum, if

1. A performance counter overflowed before an SMI
2. A PEBS record has not yet been generated because another count of the event has not occurred
3. The monitored event occurs during SMM

then a PEBS record will be saved after the next RSM instruction.

When FREEZE\_WHILE\_SMM is set, a PEBS should not be generated until the event occurs outside of SMM.

**Implication:** A PEBS record may be saved after an RSM instruction due to the associated performance counter detecting the monitored event during SMM; even when FREEZE\_WHILE\_SMM is set.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD9. APIC Error “Received Illegal Vector” May be Lost**

**Problem:** APIC (Advanced Programmable Interrupt Controller) may not update the ESR (Error Status Register) flag Received Illegal Vector bit [6] properly when an illegal vector error is received on the same internal clock that the ESR is being written (as part of the write-read ESR access flow). The corresponding error interrupt will also not be generated for this case.

**Implication:** Due to this erratum, an incoming illegal vector error may not be logged into ESR properly and may not generate an error interrupt.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.


#### **HSD10. Changing the Memory Type for an In-Use Page Translation May Lead to Memory-Ordering Violations**

**Problem:** Under complex microarchitectural conditions, if software changes the memory type for data being actively used and shared by multiple threads without the use of semaphores or barriers, software may see load operations execute out of order.

**Implication:** Memory ordering may be violated. Intel has not observed this erratum with any commercially available software.

**Workaround:** Software should ensure pages are not being actively used before requesting their memory type be changed.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD11. Performance Monitor Precise Instruction Retired Event May Present Wrong Indications**

**Problem:** When the PDIR (Precise Distribution for Instructions Retired) mechanism is activated (INST\_RETIRE.ALL (event C0H, umask value 00H) on Counter 1 programmed in PEBS mode), the processor may return wrong PEBS/PMI interrupts and/or incorrect counter values if the counter is reset with a SAV below 100 (Sample-After-Value is the [counter](#) reset value software programs in MSR IA32\_PMC1[47:0] in order to control interrupt frequency).

**Implication:** Due to this erratum, when using low SAV values, the program may get incorrect PEBS or PMI interrupts and/or an invalid counter state.

**Workaround:** The sampling driver should avoid using SAV<100.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD12. CR0.CD Is Ignored in VMX Operation**

**Problem:** If CR0.CD=1, the MTRRs and PAT should be ignored and the UC memory type should be used for all memory accesses. Due to this erratum, a logical processor in VMX operation will operate as if CR0.CD=0 even if that bit is set to 1.

**Implication:** Algorithms that rely on cache disabling may not function properly in VMX operation.

**Workaround:** Algorithms that rely on cache disabling should not be executed in VMX root operation.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD13. Instruction Fetch May Cause Machine Check if Page Size and Memory Type Was Changed Without Invalidation**

**Problem:** This erratum may cause a machine-check error (IA32\_MCI\_STATUS.MCACOD=0150H) on the fetch of an instruction that crosses a 4-KByte address boundary. It applies only if (1) the 4-KByte linear region on which the instruction begins is originally translated using a 4-KByte page with the WB memory type; (2) the paging structures are later modified so that linear region is translated using a large page (2-MByte, 4-MByte, or 1-GByte) with the UC memory type; and (3) the instruction fetch occurs after the paging-structure modification but before software invalidates any TLB entries for the linear region.

**Implication:** Due to this erratum an unexpected machine check with error code 0150H may occur, possibly resulting in a shutdown. Intel has not observed this erratum with any commercially available software.

**Workaround:** Software should not write to a paging-structure entry in a way that would change, for any linear address, both the page size and the memory type. It can instead use the following algorithm: first clear the P flag in the relevant paging-structure entry (e.g., PDE); then invalidate any translations for the affected linear addresses; and then modify the relevant paging-structure entry to set the P flag and establish the new page size and memory type.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



#### **HSD14. Execution of VAESIMC or VAESKEYGENASSIST With An Illegal Value for VEX.vvvv May Produce a #NM Exception**

**Problem:** The VAESIMC and VAESKEYGENASSIST instructions should produce a #UD (Invalid-Opcode) exception if the value of the vvvv field in the VEX prefix is not 1111b. Due to this erratum, if CR0.TS is "1", the processor may instead produce a #NM (Device-Not-Available) exception.

**Implication:** Due to this erratum, some undefined instruction encodings may produce a #NM instead of a #UD exception.

**Workaround:** Software should always set the vvvv field of the VEX prefix to 1111b for instances of the VAESIMC and VAESKEYGENASSIST instructions.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD15. Processor May Fail to Acknowledge a TLP Request**

**Problem:** When a PCIe root port's receiver is in Receiver L0s power state and the port initiates a Recovery event, it will issue Training Sets to the link partner. The link partner will respond by initiating an L0s exit sequence. Prior to transmitting its own Training Sets, the link partner may transmit a TLP (Transaction Layer Packet) request. Due to this erratum, the root port may not acknowledge the TLP request.

**Implication:** After completing the Recovery event, the PCIe link partner will replay the TLP request. The link partner may set a Correctable Error status bit, which has no functional effect.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD16. Interrupt From Local APIC Timer May Not Be Detectable While Being Delivered**

**Problem:** If the local-APIC timer's CCR (current-count register) is 0, software should be able to determine whether a previously generated timer interrupt is being delivered by first reading the delivery-status bit in the LVT timer register and then reading the bit in the IRR (interrupt-request register) corresponding to the vector in the LVT timer register. If both values are read as 0, no timer interrupt should be in the process of being delivered. Due to this erratum, a timer interrupt may be delivered even if the CCR is 0 and the LVT and IRR bits are read as 0. This can occur only if the DCR (Divide Configuration Register) is greater than or equal to 4. The erratum does not occur if software writes zero to the Initial Count Register before reading the LVT and IRR bits.

**Implication:** Software that relies on reads of the LVT and IRR bits to determine whether a timer interrupt is being delivered may not operate properly.

**Workaround:** Software that uses the local-APIC timer must be prepared to handle the timer interrupts, even those that would not be expected based on reading CCR and the LVT and IRR bits; alternatively, software can avoid the problem by writing zero to the Initial Count Register before reading the LVT and IRR bits.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD17. PCIe\* Root-port Initiated Compliance State Transmitter Equalization Settings May be Incorrect**

**Problem:** If the processor is directed to enter PCIe Polling.Compliance at 5.0 GT/s or 8.0 GT/s transfer rates, it should use the Link Control 2 Compliance Preset/De-emphasis field (bits [15:12]) to determine the correct de-emphasis level. Due to this erratum, when the processor is directed to enter Polling.Compliance from 2.5 GT/s transfer rate, it retains 2.5 GT/s de-emphasis values.

**Implication:** The processor may operate in Polling.Compliance mode with an incorrect transmitter de-emphasis level.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD18. PCIe\* Controller May Incorrectly Log Errors on Transition to RxL0s**

**Problem:** Due to this erratum, if a link partner transitions to RxL0s state within 20 ns of entering L0 state, the PCIe controller may incorrectly log an error in "Correctable Error Status.Receiver Error Status" field (Bus 0, Device 2, Function 0, 1, 2 and Device 6, Function 0, offset 1D0H, bit 0).

**Implication:** Correctable receiver errors may be incorrectly logged. Intel has not observed any functional impact due to this erratum with any commercially available add-in cards.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD19. Unused PCIe\* Lanes May Report Correctable Errors**

**Problem:** Due to this erratum, during PCIe\* link down configuration, unused lanes may report a Correctable Error Detected in Bus 0, Device 1, Function 0-2, and Device 6, Function 0, Offset 158H, Bit 0.

**Implication:** Correctable Errors may be reported by a PCIe controller for unused lanes.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD20. Accessing Physical Memory Space 0-640K through the Graphics Aperture May Cause Unpredictable System Behavior**

**Problem:** The physical memory space 0-640K when accessed through the graphics aperture may result in a failure for writes to complete or reads to return incorrect results.

**Implication:** A hang or functional failure may occur during graphics operation *such as* OGL or OCL conformance tests, 2D/3D games and graphics intensive application.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD21. PCIe Root Port May Not Initiate Link Speed Change**

**Problem:** The PCIe Base specification requires the upstream component to maintain the PCIe link at the target link speed or the highest speed supported by both components on the link, whichever is lower. PCIe root port will not initiate the link speed change without being triggered by the software when the root port maximum link speed is configured to be 5.0 GT/s. System BIOS will trigger the link speed change under normal boot scenarios. However, BIOS is not involved in some scenarios such as link disable/re-enable or secondary bus reset and therefore the speed change may not occur unless initiated by the downstream component. This erratum does not affect the ability of the downstream component to initiate a link speed change. All known 5.0Gb/s-capable PCIe downstream components have been observed to initiate the link speed change without relying on the root port to do so.

**Implication:** Due to this erratum, the PCIe root port may not initiate a link speed change during some hardware scenarios causing the PCIe link to operate at a lower than expected speed. Intel has not observed this erratum with any commercially available platform.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD22. Pending x87 FPU Exceptions (#MF) May be Signaled Earlier Than Expected**

**Problem:** x87 instructions that trigger #MF normally service interrupts before the #MF. Due to this erratum, if an instruction that triggers #MF is executed while Enhanced Intel SpeedStep® Technology transitions, Intel® Turbo Boost Technology transitions, or Thermal Monitor events occur, the pending #MF may be signaled before pending interrupts are serviced.

**Implication:** Software may observe #MF being-signalized before pending interrupts are serviced.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD23. DR6.B0-B3 May Not Report All Breakpoints Matched When a MOV/POP SS is Followed by a Store or an MMX Instruction**

**Problem:** Normally, data breakpoints matches that occur on a MOV SS, r/m or POP SS will not cause a debug exception immediately after MOV/POP SS but will be delayed until the instruction boundary following the next instruction is reached. After the debug exception occurs, DR6.B0-B3 bits will contain information about data breakpoints matched during the MOV/POP SS as well as breakpoints detected by the following instruction. Due to this erratum, DR6.B0-B3 bits may not contain information about data breakpoints matched during the MOV/POP SS when the following instruction is either an MMX instruction that uses a memory addressing mode with an index or a store instruction.

**Implication:** When this erratum occurs, DR6 may not contain information about all breakpoints matched. This erratum will not be observed under the recommended usage of the MOV SS,r/m or POP SS instructions (i.e., following them only with an instruction that writes (E/R)SP).

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



#### **HSD24. VEX.L is Not Ignored with VCVT\*2SI Instructions**

**Problem:** The VEX.L bit should be ignored for the VCVTSS2SI, VCVTSD2SI, VCVTTSS2SI, and VCVTTSD2SI instructions, however due to this erratum the VEX.L bit is not ignored and will cause a #UD.

**Implication:** Unexpected #UDs will be seen when the VEX.L bit is set to 1 with VCVTSS2SI, VCVTSD2SI, VCVTTSS2SI, and VCVTTSD2SI instructions.

**Workaround:** Software should ensure that the VEX.L bit is set to 0 for all scalar instructions.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD25. Certain Local Memory Read / Load Retired PerfMon Events May Undercount**

**Problem:** Due to this erratum, the Local Memory Read / Load Retired PerfMon events listed below may undercount.

MEM\_LOAD\_RETIRED.L3\_HIT  
MEM\_LOAD\_RETIRED.L3\_MISS  
MEM\_LOAD\_L3\_HIT\_RETIRED.XSNP\_MISS  
MEM\_LOAD\_L3\_HIT\_RETIRED.XSNP\_HIT  
MEM\_LOAD\_L3\_HIT\_RETIRED.XSNP\_HITM  
MEM\_LOAD\_L3\_HIT\_RETIRED.XSNP\_NONE  
MEM\_LOAD\_L3\_MISS\_RETIRED.LOCAL\_DRAM  
MEM\_LOAD\_L4\_RETIRED.LOCAL\_HIT  
MEM\_TRANS\_RETIRED.LOAD\_LATENCY

**Implication:** The affected events may undercount, resulting in inaccurate memory profiles. Intel has observed undercounts as much as 40%.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD26. Specific Graphics Blitter Instructions May Result in Unpredictable Graphics Controller Behavior**

**Problem:** Specific source-copy blitter instructions in Intel® HD Graphics 4600 Processor may result in unpredictable behavior when a blit source and destination overlap.

**Implication:** Due to this erratum, the processor may exhibit unpredictable graphics controller behavior. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD27. Processor May Enter Shutdown Unexpectedly on a Second Uncorrectable Error**

**Problem:** If an IA32\_MCi\_STATUS MSR contains an uncorrectable error with MCACOD=0x406 and a second uncorrectable error occurs after warm reset but before the first error is cleared by zeroing the IA32\_MCi\_STATUS MSR, a shutdown will occur.

**Implication:** When this erratum occurs, the processor will unexpectedly shut down instead of executing the machine check handler.

**Workaround:** None identified. Software should clear IA32\_MCi\_STATUS MSRs as early as possible to minimize the possibility of this erratum occurring.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



## **HSD28. Modified Compliance Patterns for 2.5 GT/s and 5 GT/s Transfer Rates Do Not Follow PCIe\* Specification**

**Problem:** The PCIe controller does not produce the PCIe specification defined sequence for the Modified Compliance Pattern at 2.5 GT/s and 5 GT/s transfer rates. This erratum is not seen at 8 GT/s transfer rates.

**Implication:** Normal PCIe operation is unaffected by this erratum.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

## **HSD29. Performance Monitor Counters May Produce Incorrect Results**

**Problem:** When operating with SMT enabled, a memory at-retirement performance monitoring event (from the list below) may be dropped or may increment an enabled event on the corresponding counter with the same number on the physical core's other thread rather than the thread experiencing the event. Processors with SMT disabled in BIOS are not affected by this erratum.

The list of affected memory at-retirement events is as follows:

MEM\_UOP\_RETIREDD.LOADS  
MEM\_UOP\_RETIREDD.STORES  
MEM\_UOP\_RETIREDD.LOCK  
MEM\_UOP\_RETIREDD.SPLIT  
MEM\_UOP\_RETIREDD.STLB\_MISS  
MEM\_LOAD\_UOPS\_RETIREDD.HIT\_LFB  
MEM\_LOAD\_UOPS\_RETIREDD.L1\_HIT  
MEM\_LOAD\_UOPS\_RETIREDD.L2\_HIT  
MEM\_LOAD\_UOPS\_RETIREDD.L3\_HIT  
MEM\_LOAD\_UOPS\_L3\_HIT\_RETIREDD.XSNP\_HIT  
MEM\_LOAD\_UOPS\_L3\_HIT\_RETIREDD.XSNP\_HITM  
MEM\_LOAD\_UOPS\_L3\_HIT\_RETIREDD.XSNP\_MISS  
MEM\_LOAD\_UOPS\_L3\_HIT\_RETIREDD.XSNP\_NONE  
MEM\_LOAD\_UOPS\_RETIREDD.L3\_MISS  
MEM\_LOAD\_UOPS\_L3\_MISS\_RETIREDD.LOCAL\_DRAM  
MEM\_LOAD\_UOPS\_L3\_MISS\_RETIREDD.REMOTE\_DRAM  
MEM\_LOAD\_UOPS\_RETIREDD.L2\_MISS

**Implication:** Due to this erratum, certain performance monitoring event will produce unreliable results during hyper-threaded operation.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.


## **HSD30. Performance Monitor UOPS\_EXECUTED Event May Undercount**

**Problem:** The performance monitor event UOPS\_EXECUTED (Event B1H, any Unmask) should count the number of UOPs executed each cycle. However due to this erratum, when eight UOPs execute in one cycle, these UOPs will not be counted.

**Implication:** The performance monitor event UOPS\_EXECUTED may reflect a count lower than the actual number of events.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD31. MSR\_PERF\_STATUS May Report an Incorrect Core Voltage**

**Problem:** The core operating voltage can be determined by dividing MSR\_PERF\_STATUS MSR (198H) bits [47:32] by  $2^{13}$ . However, due to this erratum, this calculation may report half the actual core voltage.

**Implication:** The core operating voltage may be reported incorrectly.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD32. PCIe\* Atomic Transactions From Two or More PCIe Controllers May Cause Starvation**

**Problem:** On a Processor PCIe controller configuration in which two or more controllers receive concurrent atomic transactions, a PCIe controller may experience starvation which eventually can lead to a completion timeout.

**Implication:** Atomic transactions from two or more PCIe controllers may lead to a completion timeout. Atomic transactions from only one controller will not be affected by this erratum. Intel has not observed this erratum with any commercially available device.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD33. The Corrected Error Count Overflow Bit in IA32\_MC0\_STATUS is Not Updated After a UC Error is Logged**

**Problem:** When a UC (uncorrected) error is logged in the IA32\_MC0\_STATUS MSR (401H), corrected errors will continue to update the lower 14 bits (bits 51:38) of the Corrected Error Count. Due to this erratum, the sticky count overflow bit (bit 52) of the Corrected Error Count will not get updated after a UC error is logged.

**Implication:** The Corrected Error Count Overflow indication will be lost if the overflow occurs after an uncorrectable error has been logged.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD34. An AVX Gather Instruction That Causes an EPT Violation May Not Update Previous Elements**

**Problem:** When execution of an AVX gather instruction causes an EPT (extended page table) violation due to a specific element, all previous elements should be complete. Due to this erratum, such an execution may fail to complete previous elements. In addition, the instruction's mask operand is not updated. This erratum applies only if the EPT violation occurs while updating an accessed or dirty flag in a paging-structure entry. Instructions impacted by this erratum are: VGATHERDPS, VGATHERDPD, VGATHERQPS, VGATHERQPD, VPGATHERDD, VPGATHERDQ, VPGATHERQD, and VPGATHERQQ.

**Implication:** This erratum may prevent a gather instruction from making forward progress.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD35. PLATFORM\_POWER\_LIMIT MSR Not Visible**

**Problem:** The PLATFORM\_POWER\_LIMIT MSR (615H) is used to control the PL3 (power limit 3) mechanism of the processor. Due to this erratum, this MSR is not visible to software.

**Implication:** Software is unable to read or write the PLATFORM\_POWER\_LIMIT MSR. If software attempts to access this MSR, a general protection fault will occur.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD36. LPDDR Memory May Report Incorrect Temperature**

**Problem:** When any of the four possible LPDDR ranks are not populated, the unpopulated ranks will report a default temperature of 85C as a three bit value of 011b. If the system has unpopulated ranks the temperature of memory will be reported as 85C in PCU\_CR\_DDR\_DIMM\_HOTTEST\_ABSOLUTE (MCHBAR Bus 0; Device 0; Function 0; offset 58B8H) in bits [5:7], until any of the populated ranks report a higher temperature than this.

**Implication:** When the memory temperature is less than or equal to 85C it may be reported as 85C. This erratum does not affect DDR3 and DDR3L memory types.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD37. PCIe\* Host Bridge DID May Be Incorrect**

**Problem:** The PCIe Host Bridge DID register (Bus 0; Device 0; Offset 2H) contents may be incorrect after a Package C7 exit.

**Implication:** Software that depends on the Host Bridge DID value may not behave as expected after a Package C7 exit.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD38. TSC May be Incorrect After a Deep C-State Exit**

**Problem:** On exiting from Package C6 or deeper, the processor may incorrectly restore the TSC (Time Stamp Counter).

**Implication:** Software using the TSC may produce incorrect result and/or may not behave as expected.-

**Workaround:** It is possible for BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD39. PCIe\* Controller May Initiate Speed Change While in DL\_Init State Causing Certain PCIe Devices to Fail to Train**

**Problem:** The PCIe controller supports hardware autonomous speed change capabilities. Due to this erratum, the PCIe controller may initiate speed change while in the DL\_Init state which may prevent link training for certain PCIe devices.

**Implication:** Certain PCIe devices may fail to complete DL\_Init causing the PCIe link to fail to train.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



#### **HSD40. Spurious VT-d Interrupts May Occur When the PFO Bit is Set**

**Problem:** When the PFO (Primary Fault Overflow) field (bit [0] in the VT-d FSTS [Fault Status] register) is set to 1, further faults should not generate an interrupt. Due to this erratum, further interrupts may still occur.

**Implication:** Unexpected Invalidation Queue Error interrupts may occur. Intel has not observed this erratum with any commercially available software.

**Workaround:** Software should be written to handle spurious VT-d fault interrupts.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD41. N/A. Erratum has been removed**

#### **HSD42. AVX Gather Instruction That Causes a Fault or VM Exit May Incorrectly Modify Its Destination Register**

**Problem:** An execution of a 128-bit AVX gather instruction zeroes the upper 128 bits of the instruction's destination register unless access to the first unmasked element causes a fault or VM exit. Due to this erratum, these bits may be cleared even when accessing the first unmasked element causes a fault or VM exit. Instructions impacted by this erratum are: VGATHERDPS, VGATHERDPD, VGATHERQPS, VGATHERQPD, VPGATHERDD, VPGATHERDQ, VPGATHERQD, and VPGATHERQQ.

**Implication:** Software that depends on the destination register of a 128-bit AVX gather instruction to remain unchanged after access of the first unmasked element results in fault or VM exit may not behave as expected.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD43. Inconsistent NaN Propagation May Occur When Executing (V)DPPS Instruction**

**Problem:** Upon completion of the (V)DPPS instruction with multiple different NaN encodings in the input elements, software may observe different NaN encodings in the destination elements.

**Implication:** Inconsistent NaN encodings in the destination elements for the (V) DPPS instruction may be observed.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



#### **HSD44. Display May Flicker When Package C-States Are Enabled**

**Problem:** When package C-States are enabled, the display may not be refreshed at the correct rate.

**Implication:** When this erratum occurs, the user may observe flickering on the display.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD45. Certain Combinations of AVX Instructions May Cause Unpredictable System Behavior**

**Problem:** Execution of certain combinations of AVX instructions may lead to unpredictable system behavior.

**Implication:** When this erratum occurs, unpredictable system behaviors, including system hang or incorrect results can occur.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD46. Processor May Incorrectly Estimate Peak Power Delivery Requirements**

**Problem:** Under certain conditions, the processor may incorrectly calculate the frequency at which the cores and graphics engine can operate while still meeting voltage regulator and power supply peak power delivery capabilities. When this occurs, combined with high power workloads, system shutdown may be observed.

**Implication:** When this erratum occurs, system shutdown may be observed under high power workloads.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD47. IA32\_PERF\_CTL MSR is Incorrectly Reset**

**Problem:** The IA32\_PERF\_CTL MSR (199H) is not initialized correctly after a processor reset.

**Implication:** If software reads the IA32\_PERF\_CTL MSR before writing it, software can observe an incorrect reset value. Although incorrect values are reported to software, the correct default values for this register are still used by the processor. No performance or power impact occurs due to this erratum.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.


#### **HSD48. Processor May Hang During a Function Level Reset of the Display**

**Problem:** When package C-States are enabled, it is possible that the processor may hang when software performs a Function Level Reset of the display via bit 1 of the Advanced Features Control Register (Bus 0; Device 2; Function 0; Offset 0A8H).

**Implication:** When this erratum occurs, the processor may hang.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



#### **HSD49. AVX Gather Instruction That Should Result in #DF May Cause Unexpected System Behavior**

**Problem:** Due to this erratum, an execution of a 128-bit AVX gather instruction may fail to generate a #DF (double fault) when expected. Instructions impacted by this erratum are: VGATHERDPS, VGATHERDPD, VGATHERQPS, VGATHERQPD, VPGATHERDD, VPGATHERDQ, VPGATHERQD, and VPGATHERQQ.

**Implication:** When this erratum occurs, an operation which should cause a #DF may result in unexpected system behavior.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD50. Throttling and Refresh Rate Maybe be Incorrect After Exiting Package C-State**

**Problem:** When the OLTM (Open Loop Thermal Management) feature is enabled, the DIMM thermal status reported in DDR\_THERM\_PERDIMM\_STATUS (MCHBAR Offset 588CH) may be incorrect following an exit from Package C3 or deeper.

**Implication:** The incorrect DIMM thermal status may result in degraded performance from unneeded memory throttling and excessive DIMM refresh rates.

**Workaround:** It is possible for BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD51. Processor May Livelock During On Demand Clock Modulation**

**Problem:** The processor may livelock when (1) a processor thread has enabled on demand clock modulation via bit 4 of the IA32\_CLOCK\_MODULATION MSR (19AH) and the clock modulation duty cycle is set to 12.5% (02H in bits 3:0 of the same MSR), and (2) the other processor thread does not have on demand clock modulation enabled and that thread is executing a stream of instructions with the lock prefix that either split a cacheline or access UC memory.

**Implication:** Program execution may stall on both threads of the core subject to this erratum.

**Workaround:** This erratum will not occur if clock modulation is enabled on all threads when using on demand clock modulation **or** if the duty cycle programmed in the IA32\_CLOCK\_MODULATION MSR is 18.75% or higher.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD52. IA32\_DEBUGCTL.FREEZE\_PERFMON\_ON\_PMI is Incorrectly Cleared by SMI**

**Problem:** FREEZE\_PERFMON\_ON\_PMI (bit 12) in the IA32\_DEBUGCTL MSR (1D9H) is erroneously cleared during delivery of an SMI (system-management interrupt).

**Implication:** As a result of this erratum, the performance monitoring counters will continue to count after a PMI occurs in SMM (system-management Mode).

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD53. The From-IP for Branch Tracing May be Incorrect**

**Problem:** BTM (Branch Trace Message) and BTS (Branch Trace Store) report the "From-IP" indicating the source address of the branch instruction. Due to this erratum, BTM and BTS may repeat the "From-IP" value previously reported. The "To-IP" value is not affected.

**Implication:** Using BTM or BTS reports to reconstruct program execution may be unreliable.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD54. TM1 Throttling May Continue indefinitely**

**Problem:** TM1 (Thermal Monitor 1) throttling may continue when the processor's temperature decreases below the throttling point while the processor is in Package C3 or deeper.

**Implication:** The processor will continue thermal throttling but does not indicate it is hot.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD55. Internal Parity Errors May Incorrectly Report Overflow in The IA32\_MCi\_STATUS MSR**

**Problem:** Due to this erratum, uncorrectable internal parity error reports with an IA32\_MCi\_STATUS.MCACOD (bits [15:0]) value of 0005H and an IA32\_MCi\_STATUS.MSCOD (bits [31:16]) value of 0004H may incorrectly set the IA32\_MCi\_STATUS.OVER flag (bit 62) indicating an overflow even when only a single error has been observed.

**Implication:** IA32\_MCi\_STATUS.OVER may not accurately indicate multiple occurrences of uncorrectable internal parity errors. There is no other impact to normal processor functionality.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD56. Performance Monitor Events OTHER\_ASSISTS.AVX\_TO\_SSE And OTHER\_ASSISTS.SSE\_TO\_AVX May Over Count**

**Problem:** The Performance Monitor events OTHER\_ASSISTS.AVX\_TO\_SSE (Event C1H; Umask 08H) and OTHER\_ASSISTS.SSE\_TO\_AVX (Event C1H; Umask 10H) incorrectly increment and over count when an HLE (Hardware Lock Elision) abort occurs.

**Implication:** The Performance Monitor Events OTHER\_ASSISTS.AVX\_TO\_SSE And OTHER\_ASSISTS.SSE\_TO\_AVX may over count.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.


### **HSD57. Processor May Run at Incorrect P-State**

**Problem:** The processor package may use stale software P-State (performance state) requests when one or more logical processors are idle.

**Implication:** The processor package may run at a higher or lower than expected P-State. This issue may persist as long as any logical processor is idle.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



**HSD58. Performance Monitor Event DSB2MITE\_SWITCHES.COUNT May Over Count**

**Problem:** The Performance Monitor Event DSB2MITE\_SWITCHES.COUNT (Event ABH; Umask 01H) should count the number of DSB (Decode Stream Buffer) to MITE (Macro Instruction Translation Engine) switches. Due to this erratum, the DSB2MITE\_SWITCHES.COUNT event will count speculative switches and cause the count to be higher than expected.

**Implication:** The Performance Monitor Event DSB2MITE\_SWITCHES.COUNT may report count higher than expected.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

**HSD59. Performance Monitor Register UNC\_PERF\_GLOBAL\_STATUS Not Restored on Package C7 Exit**

**Problem:** MSR\_UNC\_PERF\_GLOBAL\_STATUS (392H) is a global status register which indicates the overflow of uncore performance monitor counters. The content of this register is lost in package C7 state.

**Implication:** If any uncore performance monitor counter has overflowed before entering the package C7 state, the MSR\_UNC\_PERF\_GLOBAL\_STATUS register will no longer reflect the overflow after exiting C7 state.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

**HSD60. Processor May Not Enter Package C6 or Deeper C-states When PCIe\* Links Are Disabled**

**Problem:** If the PCIe links are disabled via Link Disable (Bus 0, Device 1, Functions [2:1], Offset B0h, bit 4) and the PCIe controller is enabled (Bus 0, Device 0, Function 0, Offset 54h, bits [2:1] = '11), then the processor will be unable to enter Package C6 or deeper C-states.

**Implication:** Due to this erratum, the process will not enter Package C6 or deeper C-states.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

**HSD61. Performance Monitor Event For Outstanding Offcore Requests And Snoop Requests May Over Count**

**Problem:** The performance monitor event OFFCORE\_REQUESTS\_OUTSTANDING (Event 60H, any Umask Value) should count the number of offcore outstanding transactions each cycle. Due to this erratum, the counts may be higher than actual number of events.

**Implication:** The performance monitor events OFFCORE\_REQUESTS\_OUTSTANDING may reflect counts higher than the actual number of events.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



## **HSD62. Some Performance Monitor Event Counts May be Inaccurate During SMT Mode**

**Problem:** The performance monitor event OFFCORE\_REQUESTS\_OUTSTANDING (Event 60H, any Umask Value) should count the number of occurrences that loads or stores stay in the super queue each cycle. The performance monitor event CYCLE\_ACTIVITY.CYCLES\_L2\_PENDING (Event A3H, Umask 01H) should count the number of cycles that demand loads stay in the super queue. However, due to this erratum, these events may count inaccurately during SMT mode.

**Implication:** The performance monitor events OFFCORE\_REQUESTS\_OUTSTANDING and CYCLE\_ACTIVITY.L2\_PENDING may be unreliable during SMT Mode.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

## **HSD63. Timed MWAIT May Use Deadline of a Previous Execution**

**Problem:** A timed MWAIT instruction specifies a TSC deadline for execution resumption. If a wake event causes execution to resume before the deadline is reached, a subsequent timed MWAIT instruction may incorrectly use the deadline of the previous timed MWAIT when that previous deadline is earlier than the new one.

**Implication:** A timed MWAIT may end earlier than expected.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

## **HSD64. The Upper 32 Bits of CR3 May be Incorrectly Used With 32-Bit Paging**

**Problem:** When 32-bit paging is in use, the processor should use a page directory located at the 32-bit physical address specified in bits 31:12 of CR3; the upper 32 bits of CR3 should be ignored. Due to this erratum, the processor will use a page directory located at the 64-bit physical address specified in bits 63:12 of CR3.

**Implication:** The processor may use an unexpected page directory or, if EPT (Extended Page Tables) is in use, cause an unexpected EPT violation. This erratum applies only if software enters 64-bit mode, loads CR3 with a 64-bit value, and then returns to 32-bit paging without changing CR3. Intel has not observed this erratum with any commercially available software.

**Workaround:** Software that has executed in 64-bit mode should reload CR3 with a 32-bit value before returning to 32-bit paging.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

## **HSD65. Performance Monitor Events HLE\_RETIREDA.BORTED\_MISC4 And RTM\_RETIREDA.BORTED\_MISC4 May Over Count**

**Problem:** The Performance Monitor Events HLE\_RETIREDA.BORTED\_MISC4 (Event C8H; Umask 40H) and RTM\_RETIREDA.BORTED\_MISC4 (Event C9H; Umask 40H) are defined to count the number of transactional aborts due to incompatible memory types. Due to this erratum, they may count additional unrelated transactional aborts.

**Implication:** The Performance Monitor Events HLE\_RETIREDA.BORTED\_MISC4 and RTM\_RETIREDA.BORTED\_MISC4 counts may be greater than the number of aborts due to incompatible memory types. This can result in nonzero counts when all memory types are compatible.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



#### **HSD66. A PCIe\* LTR Update Message May Cause The Processor to Hang**

**Problem:** If a PCIe device sends an LTR (Latency Tolerance Report) update message while the processor is in a package C6 or deeper, the processor may hang.

**Implication:** Due to this Erratum the processor may hang if a PCIe LTR update message is received while in a Package C6 or deeper.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD67. GETSEC Does Not Report Support For S-CRTM**

**Problem:** Processors with Intel® Boot Guard Technology that has GETSEC[PARAMETERS] leaf 5 EAX bit 5 set indicates support for processor rooted S-CTRM (Static Core Root of Trust for Measurement). Due to this erratum, that bit will not be set even though processor rooted S-CRTM is supported.

**Implication:** Software may be unaware of support for processor rooted S-CTRM.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD68. EPT Violations May Report Bits 11:0 of Guest Linear Address Incorrectly**

**Problem:** If a memory access to a linear address requires the processor to update an accessed or dirty flag in a paging-structure entry and if that update causes an EPT violation, the processor should store the linear address into the "guest linear address" field in the VMCS. Due to this erratum, the processor may store an incorrect value into bits 11:0 of this field. (The processor correctly stores the guest-physical address of the paging-structure entry into the "guest-physical address" field in the VMCS.)

**Implication:** Software may not be easily able to determine the page offset of the original memory access that caused the EPT violation. Intel has not observed this erratum to impact the operation of any commercially available software.

**Workaround:** Software requiring the page offset of the original memory access address can derive it by simulating the effective address computation of the instruction that caused the EPT violation.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD69. APIC Timer Might Not Signal an Interrupt While in TSC-Deadline Mode**

**Problem:** If the APIC timer is in TSC-deadline mode and is armed when a timed MWAIT instruction is executed, the timer expiration might not cause an interrupt.

**Implication:** Software depending on APIC timer TSC-deadline mode interrupts may not behave as expected.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD70. IA32\_VMX\_VMCS\_ENUM MSR (48AH) Does Not Properly Report The Highest Index Value Used For VMCS Encoding**

**Problem:** IA32\_VMX\_VMCS\_ENUM MSR (48AH) bits 9:1 report the highest index value used for any VMCS encoding. Due to this erratum, the value 21 is returned in bits 9:1 although there is a VMCS field whose encoding uses the index value 23.

**Implication:** Software that uses the value reported in IA32\_VMX\_VMCS\_ENUM[9:1] to read and write all VMCS fields may omit one field.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD71. Incorrect FROM\_IP Value For an RTM Abort in BTM or BTS May be Observed**

**Problem:** During RTM (Restricted Transactional Memory) operation when branch tracing is enabled using BTM (Branch Trace Message) or BTS (Branch Trace Store), the incorrect EIP value (From\_IP pointer) may be observed for an RTM abort.

**Implication:** Due to this erratum, the From\_IP pointer may be the same as that of the immediately preceding taken branch.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD72. VT-d Hardware May Perform STRP And SIRTTP Operations on a Package C7 Exit**

**Problem:** On a package C7 exit, VT-d hardware may spuriously perform SRTP (Set Root Table Pointer) and SIRTTP (Set Interrupt Remapping Table Pointer) operations. A package C7 exit can cause the value programmed by software in the RTA\_REG (IRTA\_REG) to be visible to hardware before software executes a GCMD.SRTP command. This will result in hardware using the new values for the DMA and interrupt translation page-walks, possibly before they are intended to be used by software.

**Implication:** If software has updated the root table pointer but has not executed the SRTP command then the root table pointer update will happen unexpectedly, causing the VMM to walk incorrect or non-existent tables. Intel has not observed this erratum with any commercially available software.

**Workaround:** Privileged software should not execute a MWAIT (because it can trigger a package C7 entry/exit) between writing to RTA\_REG (IRTA\_REG) and GCMD\_REG.SRTP (GCMD\_REG.SIRTTP) registers.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD73. General-Purpose Performance Counters Can Unexpectedly Increment**

**Problem:** A performance monitor event programmed in a general-purpose performance counter should count the number of occurrences of the event selected in IA32\_PERFVTSEL{0-7} MSR (186H-18DH). If INV (invert, bit 23) is set to 1 and a non-zero CMASK (Counter Mask) bits [31:24] value is used, due to this erratum, the event may over count in the case that either of OS (Operating System mode, bit 17) or USR (User mode, bit 16) is selected. Over counting will occur for the cycles spent in the non-matching CPL.

**Implication:** General-purpose performance counters may reflect counts higher than the actual number of events when the INV bit is set, CMASK is a non-zero value and either the OS or USR bit is set.

**Workaround:** None identified.



**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD74. Performance Monitoring Events May Report Incorrect Number of Load Hits or Misses to LLC**

**Problem:** The following performance monitor events should count the numbers of loads hitting or missing LLC. However due to this erratum, The L3\_hit related events may over count and the L3\_miss related events may undercount.

MEM\_LOAD\_RETIRED.L3\_HIT (Event D1H, Umask 40H)  
MEM\_LOAD\_RETIRED.L3\_MISS (Event D1H, Umask 20H)  
MEM\_LOAD\_L3\_HIT\_RETIRED.XSNP\_NONE (Event D2H, Umask 08H)  
MEM\_LOAD\_LLC\_MISS\_RETIRED.LOCAL\_DRAM (Event D3H, Umask 01H)

**Implication:** The listed performance monitoring events may be inaccurate.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD75. Performance Monitoring Event INSTR\_RETIRED.ALL May Generate Redundant PEBS Records For an Overflow**

**Problem:** Due to this erratum, the performance monitoring feature PDIR (Precise Distribution of Instructions Retired) for INSTR\_RETIRED.ALL (Event C0H; Umask 01H) will generate redundant PEBS (Precise Event Based Sample) records for a counter overflow. This can occur if the lower 6 bits of the performance monitoring counter are not initialized or reset to 0, in the PEBS counter reset field of the DS Buffer Management Area.

**Implication:** The above event count will under count on locked loads hitting the L2 cache.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD76. Locked Load Performance Monitoring Events May Under Count**

**Problem:** The performance monitoring events MEM\_TRANS\_RETIRED.LOAD\_LATENCY (Event CDH; Umask 01H), MEM\_LOAD\_RETIRED.L2\_HIT (Event D1H; Umask 02H), and MEM\_UOPS\_RETIRED.LOCKED (Event DOH; Umask 20H) should count the number of locked loads. Due to this erratum, these events may under count for locked transactions that hit the L2 cache.

**Implication:** The above event count will under count on locked loads hitting the L2 cache.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD77. Graphics Processor Ratio And C-State Transitions May Cause a System Hang**

**Problem:** If ratio or C-state changes involving the processor core and processor graphics occur at the same time or while processor graphics are active, under certain internal conditions the ratio change may not complete.

**Implication:** The system may hang during C-state or ratio changes.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD78. Certain Performance Monitoring Events May Over Count Software Demand Loads**

**Problem:** The following performance monitor events should count the number of software demand loads. However due to this erratum, they may also include requests from the Next Page Prefetcher and over count.

OFFCORE\_REQUESTS\_OUTSTANDING.DEMAND\_DATA (Event 60H; Umask 01H)  
OFFCORE\_REQUESTS.DEMAND\_DATA (Event B0H; Umask 01H)  
CYCLE\_ACTIVITY.L2\_Pending (Event A3H; Umask 01H)  
L2\_HIT\_MISS.LOAD (Event 24H; Umask 01H)

**Implication:** The listed performance monitoring events may reflect a count higher than the actual number of events.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD79. Accessing Nonexistent Uncore Performance Monitoring MSRs May Not Signal a #GP**

**Problem:** An access to an uncore Performance Monitor MSR beyond the number reported in the MSR\_UNC\_CBO\_CONFIG MSR (396H) bits[3:0] should signal a #GP (general-protection exception); due to this erratum, the processor may hang instead of signaling #GP.

**Implication:** When software accesses nonexistent uncore performance monitoring MSRs, the logical processor may hang instead of signaling a #GP.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD80. Call Stack Profiling May Produce Extra Call Records**

**Problem:** The performance monitoring Call Stack Profiling function should not generate call records for “zero length calls” (call instructions targeting the location following the instruction). However, due to this erratum, the processor will produce call records for zero length calls.

**Implication:** The performance monitoring LBR call stack MSRs are incorrect in the presence of “zero length calls” because calls and returns do not match.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.


### **HSD81. Warm Reset May Fail or Lead to Incorrect Power Regulation**

**Problem:** Due to this erratum, after a warm reset, the processor may fail to boot properly or may cause power to be regulated to an incorrect level.

**Implication:** The processor may not be able to control the VR (Voltage Regulator) to advertised specifications, leading to in a system hang, a machine check, or improper power regulation.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



#### **HSD82. PCIe\* Host Bridge DID May Be Incorrect**

**Problem:** The PCIe Host Bridge DID register (Bus 0; Device 0; Function 0; Offset 2H) contents may be incorrect.

**Implication:** Software that depends on the Host Bridge DID value may not behave as expected.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD83. Transactional Abort May Produce an Incorrect Branch Record**

**Problem:** If an Intel® TSX transactional abort event occurs during a string instruction, the From-IP in the LBR (Last Branch Record) is not correctly reported.

**Implication:** Due to this erratum, an incorrect From-IP on the LBR stack may be observed.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD84. SMRAM State-Save Area Above the 4GB Boundary May Cause Unpredictable System Behavior**

**Problem:** If BIOS uses the RSM instruction to load the SMBASE register with a value that would cause any part of the SMRAM state-save area to have an address above 4-GBytes, subsequent transitions into and out of SMM (system-management mode) might save and restore processor state from incorrect addresses.

**Implication:** This erratum may cause unpredictable system behavior. Intel has not observed this erratum with any commercially available system.

**Workaround:** Ensure that the SMRAM state-save area is located entirely below the 4GB address boundary.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD85. DMA Remapping Faults for the Graphics VT-d Unit May Not Properly Report Type of Faulted Request**

**Problem:** When a fault occurs during DMA remapping of Graphics accesses at the Graphics VT-d unit, the type of faulted request (read or write) should be reported in bit 126 of the FRCD\_REG register in the remapping hardware memory map register set. Due to this erratum, the request type may not be reported correctly.

**Implication:** Software processing the DMA remapping faults may not be able to determine the type of faulting graphics device DMA request.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD86. AVX Gather Instructions Page Faults May Report an Incorrect Faulting Address**

**Problem:** If software modifies a paging-structure entry to relax the access rights for a linear address and does not perform a TLB invalidation, a subsequent execution of an AVX gather instruction that accesses that address may generate a page fault that loads CR2 (which should contain the faulting linear address) with an incorrect value.

**Implication:** Software handling an affected page fault may not operate correctly.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD87. Intel® TSX Instructions May Cause Unpredictable System behavior**

**Problem:** Under certain system conditions, Intel TSX (Transactional Synchronization Extensions) instructions may result in unpredictable system behavior.

**Implication:** Due to this erratum, use of Intel TSX may result in unpredictable behavior.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD88. Event Injection by VM Entry May Use an Incorrect B Flag for SS**

**Problem:** The stack accesses made by VM-entry event injection may use an incorrect value for the B flag (default stack-pointer size and upper bound) for the stack segment (SS).

**Implication:** An affected stack access may use an incorrect address or an incorrect segment upper bound. This may result in unpredictable system behavior.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD89. A Fault in SMM May Result in Unpredictable System Behavior**

**Problem:** The value of the SS register as well as the current privilege level (CPL) may be incorrect following a fault in SMM (system-management mode). The erratum can occur only if a fault occurs following an SMI (system-management interrupt) and before software has loaded the SS register (e.g., with the MOV SS instruction).

**Implication:** This erratum may cause unpredictable system behavior. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD90. Processor Frequency is Unexpectedly Limited Below Nominal P1 When cTDP Down is Enabled**

**Problem:** When cTDP (Configurable Thermal Design Power) Down is enabled on a processor branded as Core® i3 or Pentium®, the processor frequency will be limited to cTDP Down P1 frequency (Max Non-Turbo Frequency) when it should be able to operate between the cTDP Down frequency P1 and the nominal P1 frequency.

**Implication:** When cTDP is enabled, the processor cannot achieve expected frequencies.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.


### **HSD91. PMI May be Signaled More Than Once For Performance Monitor Counter Overflow**

**Problem:** Due to this erratum, PMI (Performance Monitoring Interrupt) may be repeatedly issued until the counter overflow bit is cleared in the overflowing counter.

**Implication:** Multiple PMIs may be received when a performance monitor counter overflows.

**Workaround:** None identified. If the PMI is programmed to generate an NMI, software may delay the EOI (end-of- Interrupt) register write for the interrupt until after the overflow indications have been cleared.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD92. Execution of FXSAVE or FXRSTOR With the VEX Prefix May Produce a #NM Exception**

**Problem:** Attempt to use FXSAVE or FXRSTOR with a VEX prefix should produce a #UD (Invalid-Opcode) exception. If either the TS or EM flag bits in CR0 are set, a #NM (device-not-available) exception will be raised instead of #UD exception.

**Implication:** Due to this erratum a #NM exception may be signaled instead of a #UD exception on an FXSAVE or an FXRSTOR with a VEX prefix.

**Workaround:** Software should not use FXSAVE or FXRSTOR with the VEX prefix.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD93. RDRAND Execution in a Transactional Region May Cause a System Hang**

**Problem:** Execution of the RDRAND (Random number generator) instruction inside an Intel® TSX transactional region may cause the logical processor to hang.

**Implication:** A system hang may occur as a result of this erratum.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD94. Uncore Clock Frequency Changes May Cause Audio/Video Glitches**

**Problem:** On some processors, the time required to change the uncore clock frequency may be large enough to significantly lengthen the latency of I/O Requests to memory, possibly resulting in audio or video glitches.

**Implication:** Audio/Video glitches may occur during uncore ratio changes.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD95. Processor May Experience a Spurious LLC-Related Machine Check During Periods of High Activity**

**Problem:** Due to certain internal conditions while running core and memory intensive operations, some processors may incorrectly report an LLC (last level cache) related machine check with a IA32\_MCi\_STATUS.MCACOD value of 110AH.

**Implication:** Due to this erratum, the processor may experience a machine check.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD96. The Processor May Not Enter Package C7 When Using a PSR Display**

**Problem:** The processor datasheet specifies that entering package C7 requires enabling PSR (Panel Self Refresh) for certain display resolutions, along with other conditions. Due to this erratum, the processor may not enter package C7 when connected to a PSR-enabled display even if all of the required conditions are met.

**Implication:** Due to this erratum, the processor may not enter package C7.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD97. Video/Audio Distortion May Occur**

**Problem:** Due to this erratum, internal processor operations can occasionally delay the completion of memory read requests enough to cause video or audio streaming underrun.

**Implication:** Visible artifacts such as flickering on a video device or glitches on audio may occur.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD98. System May Hang When Audio is Enabled During Package C3**

**Problem:** When audio is enabled while in package C3 state or deeper, audio memory traffic continues to be generated. Due to this erratum, the processor logic required for memory traffic may be powered down.

**Implication:** When this erratum occurs, the processor logic required for audio memory traffic may not be operational resulting in a system hang.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD99. INVPCID May Not Cause #UD in VMX Non-Root Operation**

**Problem:** The INVPCID instruction should cause an invalid opcode exception (#UD) in VMX non-root operation if either bit 31 of the primary processor-based VM-execution controls (activate secondary controls) or bit 12 of the secondary processor-based VM-execution controls (enable INVPCID) is 0. Due to this erratum, the INVPCID instruction will not cause #UD if "activate secondary controls" is 0 and "enable INVPCID" is 1. Instead, the instruction will either execute normally or cause a VM exit if the "INVLPG exiting" VM-execution control is 1.

**Implication:** The processor may cause a VM exit that software does not expect. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.


### **HSD100. Non-Compliant PFAT Module Base Address May Cause Unpredictable System Behavior**

**Problem:** PFAT (Platform Firmware Armoring Technology) requires the PFAT module base address be 256KB aligned and reside in the first 4GB of memory. If BIOS does not comply with these requirements when setting up the PFAT module, the processor should GP# at PFAT launch. Due to this erratum, a #GP fault may not be generated.

**Implication:** A PFAT module that does not follow the PFAT module base address requirements may result in unpredictable system behavior.

**Workaround:** It is possible for the BIOS to contain a workaround for this issue.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD101. Incorrect LBR Source Address May be Reported For a Transactional Abort**

**Problem:** If the fetch of an instruction in a transactional region causes a fault, a transactional abort occurs. If LBRs are enabled, the source address recorded for such a transactional abort is the address of the instruction being fetched. If that instruction was itself the target of an earlier branch instruction, this erratum may erroneously record the address of the branch instruction as the source address for the transactional abort.

**Implication:** Trace reconstruction software that uses LBR information may fail when this erratum occurs.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD102. Address Translation Faults for Intel® VT-d May Not be Reported for Display Engine Memory Accesses**

**Problem:** The Intel® VT-d (Intel® Virtualization Technology for Directed I/O) hardware unit supporting the Processor Graphics device (Bus 0; Device 2; Function 0) may not report address translation faults detected on Display Engine memory accesses when the Context Cache is disabled or during time periods when Context Cache is being invalidated.

**Implication:** Due to this erratum, Display Engine accesses that fault are correctly aborted but may not be reported in the FSTS\_REG fault reporting register (GFXVTDBAR offset 034H).

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD103. L3 Cache Corrected Error Count May be Inaccurate After Package C7 Exit**

**Problem:** The corrected error count for L3 cache errors reported in IA32\_MCi\_STATUS.Corrected Error Count (bits [52:38]) with an MCACOD of 0001 0001 xxxx xxxx (x can be 0 or 1) may be incorrectly restored to a smaller value during exit from Package C7.

**Implication:** The corrected error count for L3 cache errors in IA32\_MCi\_STATUS may be inaccurate after Package C7 exit.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD104. PCIe\* Device's SVID is Not Preserved Across The Package C7 C-State**

**Problem:** Bus 0, Device 7, Function 0's SVID register (Subsystem Vendor Identification, Offset 2CH) is not preserved across package C7 C-State transitions.

**Implication:** This may cause the operating system to think the device has been replaced with a different device.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



#### **HSD105. Warm Reset Does Not Stop GT Power Draw**

**Problem:** Due to this erratum, if GT is enabled prior to a warm reset, it will remain powered after the warm reset. The processor will make incorrect power management decisions because it assumes the GT is not drawing power after a warm reset.

**Implication:** The processor may draw more current than expected from an external VR (Voltage Regulator). The processor may also put the external VR into a low power state where it will be unable to supply the sufficient power resulting in unpredictable system behavior.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD106. Unused PCIe\* Lanes May Remain Powered After Package C7**

**Problem:** If a PCIe controller is enabled and either has unused lanes or no PCIe device is present, the link and/or unused lanes should enter a low power state. Due to this erratum, after exiting Package C7, the unused link and/or unused lanes may remain powered.

**Implication:** Power consumption may be greater than expected.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD107. BMI1 And BMI2 Instruction Groups Are Not Available**

**Problem:** Feature flags BMI1 and BMI2 (CPUID leaf 7, sub-leaf 0, EBX bits 3 and 8) report these two groups of bit manipulation instructions are not present for the Intel® Core™ i3-4330TE but these instruction groups should be available. An attempt to execute any of these instructions will generate a #UD fault.

**Implication:** Software attempting to use any of instructions in the BMI1 and BMI2 groups will result in a #UD fault.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.


#### **HSD108. Virtual-APIC Page Accesses With 32-Bit PAE Paging May Cause a System Crash**

**Problem:** If a logical processor has EPT (Extended Page Tables) enabled, is using 32-bit PAE paging, and accesses the virtual-APIC page then a complex sequence of internal processor micro-architectural events may cause an incorrect address translation or machine check on either logical processor.

**Implication:** This erratum may result in unexpected faults, an uncorrectable TLB error logged in IA32\_MCi\_STATUS.MCACOD (bits [15:0]) with a value of 0000\_0000\_0001\_xxxxxb (where x stands for 0 or 1), a guest or hypervisor crash, or other unpredictable system behavior.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD109. Processor Energy Policy Selection May Not Work as Expected**

**Problem:** When the IA32\_ENERGY\_PERF\_BIAS MSR (1B0H) is set to a value of 4 or more, the processor will try to increase the energy efficiency of Turbo mode. However, this functionality is effectively disabled if the software requested P-state exceeds the maximum P-state supported by the processor. This has the effect of decreasing the energy efficiency of the processor while in Turbo mode.

**Implication:** When this erratum occurs, reduced battery life and reduced energy efficiency may occur.

**Workaround:** BIOS should set the max ACPI \_PST object to the max supported turbo ratio, ensuring that the software P-state request does not exceed the maximum ratio supported by the processor. Note that this workaround will disable Core Ratio Overclocking.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD110. A PEBS Record May Contain Processor State for an Unexpected Instruction**

**Problem:** If a performance counter has overflowed and is configured for PEBS (precise event-based sampling), the processor will arm the PEBS hardware within a bounded number of cycles called the skid (see the discussion of skid and related topics in the Precise Distribution of Instructions Retired section of the Intel® 64 and IA-32 Architectures Software Developer Manual). Once the PEBS hardware is armed, the processor should capture processor state in a PEBS record following the execution of the next instruction that causes the counter to increment (a “triggering” instruction). Due to this erratum, the capture of processor state may occur at an instruction after the first triggering instruction following the skid but not beyond the second triggering instruction after the skid.

**Implication:** A PEBS record may contain processor state (including instruction pointer) not associated with the triggering instruction.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD111. MSR\_PP1\_ENERGY\_STATUS Reports Incorrect Energy Data**

**Problem:** The MSR\_PP1\_ENERGY\_STATUS MSR (641H) bits [31:0] reports incorrect energy data.

**Implication:** Due to this erratum, reported Intel Integrated Graphics domain energy consumption may not be accurate.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD112. x87 FPU DP May be Incorrect After Instructions That Save FP State to Memory**

**Problem:** Under certain conditions, the value of the x87 FPU DP (Floating Point Unit Data Pointer) saved by the FSAVE/FNSAVE, FSTENV/FNSTENV, FXSAVE, XSAVE, or XSAVEOPT instructions may be incorrect.

**Implication:** Due to this erratum, the x87 FPU DP may be incorrect.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD113. Processor May Hang During Package C7 Exit**

**Problem:** Under certain internal timing conditions, the processor might not properly exit package C7 leading to a hang.

**Implication:** Due to this erratum, the package C7 state may not be reliable. Intel has not observed this erratum with any commercially available system.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD114. Intel® TSX Instructions May Cause Unpredictable System behavior**

**Problem:** Under a complex set of internal timing conditions and system events, software using the Intel TSX (Transactional Synchronization Extensions) instructions may observe unpredictable system behavior.

**Implication:** This erratum may result in unpredictable system behavior. Intel has not observed this erratum with any commercially available system.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD115. Spurious LLC Machine Check May Occur**

**Problem:** Under certain stressful conditions while running at ring ratios higher than 30, the processor may experience a spurious LLC machine check as indicated by IA32\_MCi\_STATUS.MCACOD (bits [15:0]) with value 000x 0001 0000 1010 (where x is 0 or 1).

**Implication:** When this erratum occurs, an uncorrectable LLC error will be logged and the system may hang or restart.


**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD116. Page Fault May Report Incorrect Fault Information**

**Problem:** Under the following conditions:

1. A read-modify-write instruction's memory source/destination (e.g., ADD memory, reg) crossing a cache line boundary.
2. That instruction executing without fault.
3. While the read-modify-write instruction is executing, one or more of the following page table attributes associated with its memory operand are modified:
  - a. the D (dirty) flag was 0 when the instruction was initiated but was concurrently set to 1, and/or
  - b. one of the relevant R/W flags was 0 when the instruction was initiated but was concurrently set to 1, and/or
  - c. if the read-modify-write instruction executes at CPL = 3 and one of the relevant U/S flags was 0 when the instruction was initiated but was concurrently set to 1.
4. A subsequent instruction executing within a narrow timing window that experiences a page fault
5. There is no serializing instruction between the read-modify-write instruction and the faulting instruction.



The page fault (in #4) may report an incorrect error code and faulting linear address; these would describe the read-modify-write instruction's memory access instead of that of the faulting instruction. (The address of the faulting instruction is reported correctly.)

**Implication:** The erratum makes it appear that the page fault resulted from an access that occurred prior to the faulting instruction. Because the earlier access completed without faulting, a page-fault handler may identify the page fault as transient (or spurious) and re-execute the faulting instruction (e.g., by executing IRET). In such cases, the erratum will not recur; the page fault on the later access will recur and will be reported correctly. If the page-fault handler does not re-execute the faulting instruction, this erratum may result in unpredictable system behavior. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD117. CATERR# Pin Assertion is Not Cleared on a Warm Reset**

**Problem:** If the CATERR# pin is held asserted to indicate a fatal error, a subsequent warm reset event will not cause the CATERR# pin to de-assert.

**Implication:** When this erratum occurs, platforms that monitor the CATERR# pin may be unable to detect a fatal error after a warm reset or may incorrectly respond to a CATERR# pin assertion although an error may not have occurred subsequent to the warm reset event.

**Workaround:** The CATERR# pin can be de-asserted by a cold reset event.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD118. Uncorrectable Machine Check Error During Core C6 Entry May Not be Signaled**

**Problem:** Machine Check exceptions occurring during core C6 entry may be ignored.

**Implication:** When this erratum occurs, incorrect state may be saved during core C6 entry and subsequently restored during core C6 exit resulting in unpredictable system behavior.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD119. The SAMPLE/PRELOAD JTAG Command Does Not Sample The Display Transmit Signals**

**Problem:** The Display Transmit signals are not correctly sampled by the SAMPLE/PRELOAD JTAG Command, violating the Boundary Scan specification (IEEE 1149.1).

**Implication:** The SAMPLE/PRELOAD command cannot be used to sample Display Transmit signals.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD120. Performance Monitor Event For Outstanding Offcore Requests And Snoop Requests May be Incorrect**

**Problem:** The performance monitor event OFFCORE\_REQUESTS\_OUTSTANDING (Event 60H, any Umask Value) should count the number of offcore outstanding transactions each cycle. Due to this erratum, the counts may be higher or lower than expected.

**Implication:** The performance monitor event OFFCORE\_REQUESTS\_OUTSTANDING may reflect an incorrect count.

**Workaround:** None identified.



**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD121. Processor Energy Policy Selection May Not Work as Expected**

**Problem:** When the IA32\_ENERGY\_PERF\_BIAS MSR (1B0H) is set to a value of 4 or more, the processor will try to increase the energy efficiency of Turbo mode. However, this functionality is effectively disabled if the software requested P-state exceeds the maximum P-state supported by the processor.

**Implication:** When this erratum occurs, the energy efficiency control may not behave as expected.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD122. PCIe Link May Incorrectly Train to 8.0 GT/s**

**Problem:** During PCIe\* 8.0 GT/s Phase 2 Equalization training, the received per-lane transmitter coefficients for physical lanes 8-15 may be incorrectly applied to the PCIe transmitters.

**Implication:** Due to this erratum, a PCIe link may either fail to train to the 8.0 GT/s transfer speed, experience link errors, or periodically retrain (possibly dropping to a lower link speed).

**Workaround:** A BIOS code change has been identified and may be implemented as a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

#### **HSD123. PCIe Tx Voltage Reference Cannot be Changed**

**Problem:** PCIe\* Tx Voltage Reference Select is available via the PCIE\_CR\_AFEBCND[0:7]CFG1 (Device 1; Function 0) registers in field TxVrefSel bits [9:5]. Due to this erratum, changes to these values will have no effect.

**Implication:** For PCIe, setting the Tx Voltage Reference Select to non-default values will not produce the reference levels documented in the register description. Tx swing control utilizes Tx Voltage Reference; Tx swing cannot be adjusted from default.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Table of Changes*.


#### **HSD124. VM Exit May Set IA32\_EFER.NXE When IA32\_MISC\_ENABLE Bit 34 is Set to 1**

**Problem:** When "XD Bit Disable" in the IA32\_MISC\_ENABLE MSR (1A0H) bit 34 is set to 1, it should not be possible to enable the "execute disable" feature by setting IA32\_EFER.NXE. Due to this erratum, a VM exit that occurs with the 1-setting of the "load IA32\_EFER" VM-exit control may set IA32\_EFER.NXE even if IA32\_MISC\_ENABLE bit 34 is set to 1. This erratum can occur only if IA32\_MISC\_ENABLE bit 34 was set by guest software in VMX non-root operation.

**Implication:** Software in VMX root operation may execute with the "execute disable" feature enabled despite the fact that the feature should be disabled by the IA32\_MISC\_ENABLE MSR. Intel has not observed this erratum with any commercially available software.

**Workaround:** A virtual-machine monitor should not allow guest software to write to the IA32\_MISC\_ENABLE MSR.

**Status:** For the steppings affected, see the *Summary Table of Changes*.



### **HSD125. Re-enabling eDRAM May Log a Machine Check and Hang**

**Problem:** If the eDRAM was disabled as a result of a package C-State entry of C2 or higher or a software request, the subsequent package C-state exit or software request to re-enable eDRAM may result in a machine check logged in IA32\_MCI\_STATUS.MCACOD [15:0] with of value 402H and subsequent system hang.

**Implication:** Due to this erratum, the system may log a machine check and hang.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD126. Warm Reset Does Not Stop EDRAM Power Draw**

**Problem:** Due to this erratum, if EDRAM is enabled prior to a warm reset, it will remain powered after the warm reset. The processor will make incorrect power management decisions because it assumes the EDRAM is not drawing power after a warm reset.

**Implication:** The processor may draw more current than expected from an external VR (Voltage Regulator). The processor may also put the external VR into a low power state where it will be unable to supply the sufficient power resulting in unpredictable system behavior.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD127. Opcode Bytes F3 0F BC May Execute As TZCNT Even When TZCNT Not Enumerated by CPUID**

**Problem:** If CPUID.(EAX=07H, ECX=0):EBX.BMI1 (bit 3) is 1 then opcode bytes F3 0F BC should be interpreted as TZCNT otherwise they will be interpreted as REP BSF. Due to this erratum, opcode bytes F3 0F BC may execute as TZCNT even if CPUID.(EAX=07H, ECX=0):EBX.BMI1 (bit 3) is 0.

**Implication:** Software that expects REP prefix before a BSF instruction to be ignored may not operate correctly since there are cases in which BSF and TZCNT differ with regard to the flags that are set and how the destination operand is established.

**Workaround:** Software should use the opcode bytes F3 0F BC only if CPUID.(EAX=07H, ECX=0):EBX.BMI1 (bit 3) is 1 and only if the functionality of TZCNT (and not BSF) is desired.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

### **HSD128. Intel® S2DDT May Not Function Correctly with Certain High Resolution Displays**

**Problem:** A limitation in Intel S2DDT (Intel® Smart 2D Display Technology), commonly known as frame buffer compression, may result in pixel data being supplied too slowly to the display.

**Implication:** Screen flickering or blank screen may be observed on certain high resolution displays.

**Workaround:** The latest version of the Intel graphics driver disables Intel S2DDT for resolutions with a pixel clock between 513 MHz and 540 MHz.

**Status:** For the steppings affected, see the *Summary Table of Changes*.

**Status:**





# Specification Changes


---

The Specification Changes listed in this section apply to the following documents:

- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 1: Basic Architecture*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2A: Instruction Set Reference Manual A-M*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2B: Instruction Set Reference Manual N-Z*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3B: System Programming Guide*

There are no new Specification Changes in this Specification Update revision.





# Specification Clarifications

---

The Specification Clarifications listed in this section may apply to the following documents:

- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 1: Basic Architecture*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2A: Instruction Set Reference Manual A-M*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2B: Instruction Set Reference Manual N-Z*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3B: System Programming Guide*

There are no new Specification Changes in this Specification Update revision.





# Documentation Changes

---

The Documentation Changes listed in this section apply to the following documents:

- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 1: Basic Architecture*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2A: Instruction Set Reference Manual A-M*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2B: Instruction Set Reference Manual N-Z*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3B: System Programming Guide*

All Documentation Changes will be incorporated into a future version of the appropriate Processor documentation.

**Note:** Documentation changes for Intel® 64 and IA-32 Architecture Software Developer's Manual volumes 1, 2A, 2B, 3A, and 3B will be posted in a separate document, Intel® 64 and IA-32 Architecture Software Developer's Manual Documentation Changes. Use the following link to become familiar with this file: <http://developer.intel.com/products/processor/manuals/index.htm>

There are no new Documentation Changes in this Specification Update revision.

## **HSD1. On-Demand Clock Modulation Feature Clarification**

Software Controlled Clock Modulation section of the Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3B: System Programming Guide will be modified to differentiate On-demand clock modulation feature on different processors. The clarification will state:

For Hyper-Threading Technology enabled processors, the IA32\_CLOCK\_MODULATION register is duplicated for each logical processor. In order for the On-demand clock modulation feature to work properly, the feature must be enabled on all the logical processors within a physical processor. If the programmed duty cycle is not identical for all the logical processors, the processor clock will modulate to the highest duty cycle programmed for processors if the CPUID DisplayFamily\_DisplayModel signatures is listed in Table 14-2. For all other processors, if the programmed duty cycle is not identical for all logical processors in the same core, the processor will modulate at the lowest programmed duty cycle.

For multiple processor cores in a physical package, each core can modulate to a programmed duty cycle independently.

For the P6 family processors, on-demand clock modulation was implemented through the chipset, which controlled clock modulation through the processor's STPCLK# pin.

Table 14-2. CPUID Signatures for Legacy Processors That Resolve to Higher Performance Setting of Conflicting Duty Cycle Requests



Display Family Display Model	Display Family Display Model	Display Family Display Model	Display Family Display Model
0F_xx	06_1C	06_1A	06_1E
06_1F	06_25	06_26	06_27
06_2C	06_2E	06_2F	06_35
06_36			

§ §

