


TRB3200-TR50	TRB/BNC Plug Clamp	
		
Parts	Material	Plating (Micro-inch)
Nut	Brass	Nickel Over Copper
Contact Pin	Brass	Gold 5 Over Nickel 50 Over Copper 50
Braid Clamp	Brass	Nickel Over Copper
Insulator	Teflon	
Body	Brass	Nickel Over Copper
Contact Body	Brass	Nickel Over Copper
Gasket	Silicon	
Spring	SK5	Nickel Over Copper
Washer	Brass	Nickel Over Copper
Coupling Nut	Brass	Nickel Over Copper
<b>Weight:</b> Suitable Cables: Triax-5001, TRC-50-1		

**This part number complies with RoHS.**

**Notice: JYEBAO reserves the right to make modifications deemed appropriate.**

# JYE BAO CO., LTD.

## CABLE ASSEMBLY INSTRUCTION
























TRB3200-TR50					DATE	2015/06/30		REV	—			
A	B	C	D	E	F	G	H	I	J	K	L	
												
BODY	INSULATOR	CONTACT BODY	INSULATOR	CONTACT PIN	INSULATOR	BRAID CLAMP	INSULATOR	BRAID CLAMP	GASKET	WASHER	NUT	

DIAGRAM	ASSEMBLY INSTRUCTION
	Step 1: STRIP AS SHOWN.
	Step 2: SLIDE NUT "L" - WASHER "K" - GASKET "J" AND OVER CABLE.
	Step 3: WRAP THE BRAIDING BACKWARD OVER GASKET "J".
	Step 4: SLIDE TOP HAT "I" BETWEEN BRAIDING AND DIELECTRIC.
	Step 5: STRIP AS SHOWN.
	Step 6: SLIDE INSULATOR "H" AND BRAID CLAMP "G" OVER CABLE.
	Step 7: WRAP THE BRAIDING OVER "G".
	Step 8: STRIP AS SHOWN.
	Step 9: PUT INSULATOR "F" - CONTACT PIN "E" ON CENTER CONDUCTOR AND SOLDER IN "Y".
	Step 10: SLIDE PREPARED CABLE INTO INSULATOR "D" - CONTACT BODY "C" - INSULATOR "B".
	Step 11: FINALLY SCREW "L" ON THE CONNECTOR BODY "A".

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

APPROVED	CHECKED	DRAWING
		<i>Albert</i>