



Parts	Material	Plating(Micro-inch)
Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Washer	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Gasket	Silicon	
Top Hat	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Contact Pin	Brass	Silver 150 Over Copper 50
Insulator	Teflon	
Body	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Coupling Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50

Weight:

Suitable Cables: RG8,RG213

This part numner complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



## **CABLE ASSEMBLY INSTRUCTION** HN3200-0213 JYE BAO CO., LTD. С F Α В D Ε **BODY CONTACT PIN** TOP HAT **GASKET** WASHER NUT **DIAGRAM** ASSEMBLY INSTRUCTION Step 1: STRIP AS SHOWN. 5.5 [.217] D Step 2: SLIDE " D ", " E ", " F " OVER CABLE. 5 [.197] Step 3: SLIDE " C " BETWEEN BRAIDING AND DIELECTRIC. BRAIDING Step 4: STRIP THE DIELECTRIC AS SHOWN. Step 5: PUT PIN " B " ON CENTER CONDUCTOR AND SOLDER IN " Y ". Α Step 6: FINALLY SCREW " F " ON THE CONNECTOR BODY "A".

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.