Home
Part Number Search
Document Search
CAD Model Search
Text Search
Alternate/Lead Free Part Search
Multiple Part Comparison
Alphabetical Search
Brand Search
Industry Product Search
Product Type Search
Product Family Search
Competitor Cross Reference
Lead Free Solutions
Tool Search
Help/Glossary

AMP-BLADE Connectors and Contacts

AMP-BLADE Two-Piece Printed Circuit Edge Connectors and Contacts

AMP **1-582261-4** Active Active Not Reviewed for ELV/RoHS Compliance

(Tyco Electronics P/N: 1-582261-4)

Search for Parts

Document links for this part cannot be displayed. Your browser does not support inline frames or is currently configured not to display inline frames. Inline frames are supported in both Internet Explorer 5 and Netscape 6, as well as all later versions of these browsers.

Related Part Information

General Information	eCommerce	Related Part Information
General Info Sales Info Assembly Subcontractors	Pricing Product Availability	Tooling

Searchable Features:	
Brand:	AMP
Government/Industry Qualification:	No
RoHS/ELV Compliance:	Not reviewed for compliance
Lead Free Solder Process:	Not reviewed for lead free solder process
Product Type:	Contact
Contact Type:	Post-Type
Contact Mating Area Plating:	Gold (30)
Packaging Method:	Loose Piece
Post Size (mm [in]):	0.79 x 1.57 [.031 x .062]
Mating Post Length (mm [in]):	25.40 [1.000]

Other Properties:	
Proprietary Name:	AMP-BLADE
Contact Material:	Phosphor Bronze

Copyright and Privacy Statement

Visit Tyco International, Ltd.

i2 Technologies US, Inc.
15445 Innovation Drive
San Diego, CA 92128

i2 Technologies US, Inc.

HTML Pages converted to PDF Document

This document contain component information from the manufacturer's website which are not available in a revision controlled document from the manufacturer. To facilitate the addition of these parts into the Electronics Database, we are converting the HTML pages related to that part, from the manufacturer's website into Adobe PDF format. The contents of this document is based on the information provided on the manufacturer's website, therefore the information may have been changed by the manufacturer since this was created.