


# CURRENT SENSE TRANSFORMERS

## 7200 SERIES

Miller Number	Current Range Amps	Freq. Range kHz	Load Res. Ohms	Sec. Turns	Sec. L (mH) Min.	Sec. DCR Ohms
7201	2 - 10	5 - 50	50	50	5	.7
7202	2 - 20	5 - 50	100	100	20	1.4
7203	2 - 35	1 - 100	200	200	80	3.8



Dimensions are in mm

