

## Terminals and Splices

### AMPOWER Splices

AMP 1-324453-0 Active [Active](#)

RoHS Compliant [RoHS Compliant](#)

**(Tyco Electronics P/N: 1-324453-0)**

[Search for Parts](#)

Document links for this part cannot be displayed. Your browser does not support inline frames or is currently configured not to display inline frames. Inline frames are supported in both Internet Explorer 5 and Netscape 6, as well as all later versions of these browsers.

#### Related Part Information

General Information	eCommerce	Related Part Information
<a href="#">General Info</a> <a href="#">Sales Info</a> <a href="#">Assembly Subcontractors</a>	<a href="#">Pricing</a> <a href="#">Product Availability</a>	<a href="#">Tooling</a>

#### Searchable Features:

<b>Brand:</b>	AMP
<b>RoHS/ELV Compliance:</b>	RoHS compliant, ELV compliant
<b>Lead Free Solder Process:</b>	Not relevant for lead free process
<b>Splice Type:</b>	Parallel
<b>Wire Size (AWG/CM):</b>	700,000 CM
<b>Barrel Length:</b>	Standard
<b>Barrel I.D. Min. (mm [in]):</b>	29.77 [1.172]

#### Other Properties:

<b>RoHS/ELV Compliance History:</b>	Always was compliant
<b>Wire Range (CMA):</b>	650,000 – 750,000
<b>Material:</b>	Copper
<b>Finish:</b>	None
<b>Comment:</b>	Two Crimps necessary. Annealed Copper per ASTM B-188.

[Copyright](#) and [Privacy Statement](#)

Visit [Tyco International, Ltd.](#)

[Products](#) | [Catalog](#) | [Brands](#) | [Industries](#) | [Commerce](#) | [Supplier](#) | [Contact Us](#) | [About](#) | [Home](#)

# i2 Technologies US, Inc.

## HTML Pages converted to PDF Document

This document contains component information from the manufacturer's website which are not available in a revision controlled document from the manufacturer. To facilitate the addition of these parts into the Electronics Database, we are converting the HTML pages related to that part, from the manufacturer's website into Adobe PDF format. The contents of this document is based on the information provided on the manufacturer's website, therefore the information may have been changed by the manufacturer since this was created.

