


High Voltage SHV-NIM

Hochspannung SHV-NIM

Straight Jack, clamp

Kuppler gerade, klemm


Part Number	Cable Group	Assembly Instruction	Remarks	Packing Unit
57 K 101-006 A3	06,07,08	57 A	–	1
57 K 101-009 A3	09	57 A	–	1



Straight Jack, crimp

Kuppler gerade, crimp


Part Number	Cable Group	Assembly Instruction	Crimp-Inserts	Remarks	Packing Unit
57 K 101-106 A3	06,07,08	57 B	11 W 150-206	a = 13.5, b = 55.5	1
57 K 101-109 A3	09	57 B	11 W 150-209	a = 12, b = 54	1



Flange Plug

Flanschstecker

Part Number	Panel Piercing	Remarks	Packing Unit
57 S 401-200 A3	B 6	4 x 3-56, centering collar, dia 11	1



Bulkhead Plug

Einbaustecker

Part Number	Panel Piercing	Remarks	Packing Unit
57 S 501-200 A3	B 2	–	1

