


High Voltage SHV

Hochspannung SHV

Straight Plug, clamp

Stecker gerade, klemm


Part Number	Cable Group	Assembly Instruction	Remarks	Packing Unit
41 S 102-006 A1	06,07,08	41 A	–	1
41 S 102-009 A1	09	41 A	–	1



Straight Jack, clamp

Kuppler gerade, klemm

Part Number	Cable Group	Assembly Instruction	Remarks	Packing Unit
41 K 102-006 A3	06,07,08	41 B	–	1
41 K 102-009 A3	09	41 B	–	1



Bulkhead Jack

Einbaukuppler

Part Number	Panel Piercing	Remarks	Packing Unit
41 K 501-200 A3	B1	–	1

