



Straight Jack for Corrugated Cables Kuppler gerade, für Wellmantel-Kabel


Part Number	Cable Group	Assembly Instruction	Remarks	Packing Unit
60 K 114-C07 N1	C07	60 21	—	1

**Straight Jack for Corrugated Cables Kuppler gerade, für Wellmantel-Kabel**


Part Number	Cable Group	Assembly Instruction	Remarks	Packing Unit
60 K 114-C09 N1	C09	60 15	—	1

**Flange Jack, crimp****Flansch-Kuppler, crimp**

Part Number	Cable Group	Assembly Instruction	Panel Piercing	Crimp-Inserts	Remarks	Packing Unit
60 K 431-315 N1	15	60 B4	B 46	11 W 150-115	4 x dia. 3.6	1
60 K 431-317 N1	17	60 B4	B 46	11 W 150-115	4 x dia. 3.6	1

**Flange Jack for Corrugated Cables Flansch-Kuppler für Wellmantel-Kabel**

Part Number	Cable Group	Assembly Instruction	Remarks	Packing Unit
60 K 454-C01 N1	C01	53 A1	—	1

**Flange Jack****Flansch-Kuppler**

Part Number	Cable Group	Assembly Instruction	Panel Piercing	Remarks	Packing Unit
60 K 40B-272 B1	72	60 E9	B 46	—	1

