

1-2-2 3-Phase Motor Driver ICs


Part No.	Output Current (A)	Supply Voltage (V)	Step Sequence Mode	Package	Remarks	Fig. No.
SI-7600	3.0	15~45	2-phase/2-3 phase excitation	SOP20Pin	Use in pair with SLA5017, etc.	1
SI-7600D				DIP20Pin		2
SLA-7611M				ZIP18Pin With Fin		3

1-2-3 5-Phase Motor Driver Control ICs


Part No.	Supply Voltage (V)	Step Sequence Mode	Package	Remarks	Fig. No.
SI-7502	15~42	For pentagonal connection drive	Powder coating 27pin	Use with SLA6503 and SLA5011	4

External Dimensions


• No. 1




• No. 2



• No. 3



No. 4



(unit: mm)