






CABLE ASSEMBLY INSTRUCTION

BNC8105T-0059

JYE BAO CO., LTD.



| DIAGRAM | ASSEMBLY INSTRUCTION |
|---|---|
|  | <p>Step 1: STRIP AS SHOWN.</p> |
|  | <p>Step 2: SLIDE FERRULE "A" OVER CABLE. Step 3: PUT PIN " B " ON CENTER CONDUCTOR AND SOLDER IN " Y " OR CRIMP IN " X " .</p> |
|  | <p>Step 4: LOOSEN BRAIDING AND SLIDE CONNECTOR "C" IN PLACE.</p> |
|  | <p>Step 5: SLIDE FERRULE "A" TOWARDS THE CONNECTOR AND CRIMP.</p> |

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.