



Weight: 2.76 g

Suitable Cables: RD316, RG316D-E, RD316-FEP, JBY100

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION SMB3100AD-9316 JYE BAO CO., LTD. В Α D **FERRULE BODY** COVER DIAGRAM ASSEMBLY INSTRUCTION Step 1: STRIP AS SHOWN. 4.2 [.165] Step 2: SLIDE FERRULE "B" OVER CABLE. Step 3: WRAP THE BRAIDING UPWARDS. Step 4: SLIDE CENTER CONDUCTOR ON THE CONTACT PIN OF CONNECTOR "A" AND SOLDER IN "Y". Step 5: SLIDE FERRULE "B" TOWARDS THE CONNECTOR "A" AND CRIMP. FORCE Step 6: PRESS ON THE TOP OF "D" WITH JIGS.

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.