



Parts	Material	Plating (Micro-inch)
Ferrule	Brass	Gold 5 Over Nickel 50 Over Copper 50
Contact Pin	Phosphor Bronze	Gold 20 Over Nickel 50 Over Copper 50
Barrel	Brass	Gold 5 Over Nickel 50 Over Copper 50
Insulator	Teflon	
Body	Brass	Gold 5 Over Nickel 50 Over Copper 50
Coupling Nut	Brass	Gold 5 Over Nickel 50 Over Copper 50

Weight:

Suitable Cables: RG55, RG142, RG400, RG142-E

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



## CABLE ASSEMBLY INSTRUCTION SMC3100-0142 JYE BAO CO., LTD. В Ε Α FERRULE **CONTACT PIN** BODY \*TOOLS AND FIXTURES ARE REFERENCE ON PAGE 306 OF JYEBAO'S 2005 CATALOG. DIAGRAM ASSEMBLY INSTRUCTION 4.65 [.183] 2.5 [.098] Step 1: STRIP AS SHOWN. В Ε Step 2: SLIDE FERRULE "B " OVER CABLE. Step 3: PUT PIN " E " ON CENTER CONDUCTOR AND CRIMP IN "Y". Step 4: LOOSEN BRAIDING AND SLIDE CONNECTOR "A" IN PLACE. В Step 5: SLIDE FERRULE "B" TOWARDS THE CONNECTOR " A " AND CRIMP.

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.