Part No

24.0115

23.506!

23.0440

Туре

A 2/4

1:1

B4-I/K

Nominal diameter	Withdraw. force	Rated current	Contact resistance				
4 mm	-	25 A	$0.6~\text{m}\Omega$				
versal adapter, 2 mm (.080 in) dia. Multilam™ plug							

Universal adapter, 2 mm (.080 in) dia. Multilam™ plug on one end and 4 mm (.160 in) dia. in-line socket on the other end.

Machined brass, gold plated and polyamide insulated. Used with standard or safety plugs.

Operating temperature: -40°C to +80°C (-40°F to 176°F)

Colors: 21 - 24

11 25 22 36


4 mm

Universal adapter, 4 mm (.160 in) dia. suitable for 4 mm (.160 in) dia. plugs. Terminal can be connected to threaded clamps with bolt diameters of 4, 6 and 8 mm (.160, .236 and .315 in).

Made of brass, gold plated and polyamide insulated.

Operating temperature:-40°C to +80°C (-40°F to 176°F)

Colors: 21 - 24



1:1


B4-I/KA

4 mm

Adapter suitable for screw terminals with screw diameter up to 6 mm (.236 in) dia. Socket fits any commercial spring-loaded 4 mm (.160 in) dia. plug. Made of brass, gold plated with polyamide insulation.

Operating temperature: -40°C to +80°C (-40°F to 176°F)

Colors: 21 - 24



1:1.3

Adapters

Nominal Withdraw. Rated Contact 'art No. Type diameter force current resistance **B 4-1/KS** 23.0480 4 mm Adapter suitable for screw terminals with screw diameter up to 3.6 mm (.141 in) dia. Socket fits any commercial spring-loaded 4 mm (.160 in) dia. plug. Made of brass, nickel plated with PA (polyamide) insulation. 24,5 Operating temperature: -40°C to +80°C (-40°F to 176°F) Colors: 21 - 24 37 1:1 36.9690 XKS-4 4 mm 20 A Safety spade terminal, rated 1000 V, CAT II, 20 A, has a tin-plated solid copper spade especially designed for დ↓ terminal strips, with an in-line safety socket. /!ackslash During installation, the terminal must be at zero potential. Colors: 21 - 27, 29 1:1 36.9126 XKS-A 4 mm 20 A 55.5 Safety spade terminal, rated 1000 V, CAT II, 20 A, has a nickel-plated brass spade especially designed for binding posts, with an in-line safety socket. During installation, the terminal must be at zero potential. Colors: 21 - 27, 29 1:1 36.9691 **XKS-8 N** 4 mm 30 A Safety spade terminal, rated 1000 V, CAT II, 30 A, has a nickel-plated brass spade especially designed for screw terminals, with an in-line safety socket. During installation, the terminal must be at zero potential. Colors: 21 - 27, 29 1:1

25 - green 26 - violet 27 - brown 28 - gray 29 - white 33 - transparent

20 - green/yellow 21 - black 22 - red 23 - blue 24 - yellow

Nominal diameter	Withdraw. force	Rated current	Contact resistance			Туре	Part No
2 mm 4 mm	-	19 A 32 A	-			KK 2/4 KK 4/4	24.014 1 (KK 2/4
Universal coupler K socket on one end 4 end and KK 4/4 with both ends.	mm (.160	in) dia. soo	ket on other		25		24.014 2 (KK 4/4
Ratings for KK 2/4: • Test voltage:	••••••				8 3		
Operating tempera	nture:		0°C to +80°C 4°F to 176°F)		40		
Ratings for KK 4/4: •Rated voltage: (valid only when c • Insulation coordin • Test voltage: • Operating tempera	onnected to ation:	MC safety	plugs.) 6000 V/2 3250 V		\$ \$ 40		
Colors: 21 - 24			4°F to 176°F)			1:2	
4 mm Safety in-line coupl special profile on the connection is maint leads.	ne central se	ction to en	sure a secure		62.5 	ХНК	66.912
Colors: 21 - 27, 19	l			Hele		1:1	
4 mm 2 mm	-	-	-	Multilines" Equipped		RS-4/2 A	63.9226
2mm Multilam TM pl accepts all HCK sta Polyamide 6.6 insu Weight: 3.7 g.	ndard and s			e e e e e e e e e e e e e e e e e e e	STEP STEP STEP STEP STEP STEP STEP STEP		
Colors: 21 - 23						1:1	
4 mm 2 mm		_	-	Multilann** Equipped	4 15.5 19 19 19 19 19 19 19 1	AS-2/4	63.9227
Adapter with 4mm accept Multilam™ profile provides a s Weight: 4.2 g.	or hollow pl	ugs. The a	dapter's low		S TUN 3		
Colors: 21 - 23				nek		1:1	

4 mm

Adapters

Nominal Withdraw. Rated Contact 'art No. Type diameter force current resistance 22.5163 LS 410-I 4 mm 25 A $0.8 \, \text{m}\Omega$ Multilam™ plug 4 mm (.160 in) dia.with in-line socket 4 mm (.160 in) dia. Nickel plated. Polyamide insulated. 20 Colors: 21, 22 18 4 9 46 1:1 36.9129 KSA-4/19 4 mm 30 A KSA-4/27 KSA-4/19) Low voltage adapters, rated 30 Vac / 60 Vpc, CAT II, 36.9128 30A, have an insulated safety socket and a 4 mm KSA-4/27) Multilam™ plug. Two different lengths of plugs are 21 HCK available. The longer 27 mm plug (KSA-4/27) is 61 especially suitable for deep mounted sockets. These adapters are fitted with a low withdrawal force Multilam™ so that the adaptor is retained on the lead HCK \$1 when disconnecting it from the instrument When using this adapter with safety test leads, the overall voltage rating is reduced to 30 VAC / 60 VDC. 1:1 Colors: 21 - 25 36.9122 **XUG** 4 mm 30 A Low voltage adapter, rated 30 Vac / 60 Vpc, CAT II, 30A, 58.5 23 with an insulated safety socket and a 4 mm Multilam™ plug. The adapter is fitted with high withdrawal force Multilam™ so that the adapter is retained in the socket when disconnecting the lead.


20 - green/yellow 21 - black 22 - red 23 - blue 24 - yellow 25 - green 26 - violet 27 - brown 28 - gray 29 - white 33 - transparent

1:1

Colors: 21 - 27, 29

When using this adapter with safety test leads, the overall voltage rating is reduced to 30 VAC / 60 VDC.

Nominal diameter	Withdraw. force	Rated current	Contact resistance		Туре	Part No
4 mm 2mm	-	25 A	$1.0~\text{m}\Omega$	Equipped	R 4/2	24.011(
Adapter 4 mm (.16 reduce 4 mm to 2 machined brass, go Polyamide insulate	mm socket. old plated wit	th MC®-Mเ		16		
Operating temperat	ture:		0°C to +70°C 4°F to 158°F)		4/2-F	24.0107
Colors: (R4/2-A on	ly): 21 - 24			(internal Multila	ım™)	



1:1


22.3000


4 mm _ _ _ _ _

Fits any 4 mm (.160 in) dia. socket. Tapping from rear is possible simultaneously with spring-loaded 2 mm (.080 in) and 4 mm (.160 in) dia. plugs.

Components and ratings:

Colors: 21 - 29






1:1

a mm

Adapters



Type


Part No

24.0162

Nominai diameter	force	current	resistance		
4 mm	_	_	_		

Adapter 4 mm (.160 in) dia. suitable for connecting terminal blocks. Suitable for all 4 mm (.160 in) patch cords. Socket machined brass, nickel plated, with PVC insulated copper wire 2.25 mm (.089 in) dia. Polyamide insulated.

Color: 21




4 mm - 25 A -

Terminal adapter with 4 mm (.160 in) plug and 4 mm (.160 in) dia. in-line socket. Machined brass, nickel plated. Suitable for all spring-loaded 4 mm (.160 in) patch cords.

Polyamide insulated.

Color: 21




4 mm – 25 A

Terminal adapter 4 mm (.160 in) dia. with M 3.5 thread Made of brass, nickel plated, suitable for all springloaded 4 mm (.160 in) dia. patch cords and safety patch cords.

Polyamide insulated.

Colors: 21 - 24



1:1


Adapters

'art No.

24.0160

Type

A-SLK 4



Nominal diameter force

Withdraw. Rated current

Contact resistance

4 mm

Safety adapter 4 mm (.160 in) dia. for connecting MC safety patch cords SLK with all conventional sockets, jacks and binding posts 4 mm (.160 in) dia. Expanding plug with internal screw for assembly with sockets, jacks and binding posts 4 mm (.160 in) dia. Gold plated. Polyamide insulated.

Colors: 20 - 29

1:1.3

1:1.3


Tool, special allen wrench:

• StS 1.5-I (insulated) # 25.0037

• StS 1.5 (non-insulated) # 25.0035

24.0163

A-SLK 4-S



4 mm

Safety adapter 4 mm (.160 in) dia. for connecting MC safety patch cords SLK with all conventional sockets, jacks and binding posts 4 mm (.160 in) dia. Expanding plug with internal screw for assembly with sockets, jacks and binding posts 4 mm (.160 in) dia. Nickel plated. Polyamide insulated.

Colors: 21 - 24

Tool, special allen wrench:

• StS 1.5-I (insulated) # 25.0037


• StS 1.5 (non-insulated) # 25.0035

i6.9140-000 ASA-M4)

6.9140-001 ASA-M6)

6.9140-002 ASA-M8)

ASA-M4 ASA-M6 ASA-M8



4 mm

Screw-on adapter, rated 1000 V, CAT II, has a 4 mm safety socket and is available with an option of three internal metric threads for screwing on to protruding screw threads. The adapter has a polyamide 6.6 insulator.

/!\ During installation, the terminal must be at zero potential.

Current Ratings:

• ASA-M4 20 A • ASA-M6 30 A • ASA-M8 30 A

Colors: 21 - 26

1:2

Part No

66.9610

23.1031

23.1032

23.1033

(B4-E-M4-I) 23.1034

(B4-E-M5-I

(B4-E-M3-I

(B4-E-M3.5-I

Type

KSA-M4/6


Nominal	Withdraw.	Rated	Contact resistance		
diameter	force	current			
4 mm	-	20 A	_		

Screw-in adapters, rated 1000 V, CAT II, 20 A, have an insulated safety socket with a M4 male thread in an option of two lengths. These adapters are recommended for installing a permanent plug-in connection, for example on experimental boards or on terminal blocks.

 Λ

During installation, the terminal must be at zero potential.

Colors: 21 - 23



4 mm - 32 A -

Screw-in adapters with 4 mm diameter safety socket for accepting 4 mm diameter safety test leads or any other 4 mm Multilam™ plug. The metal socket has an internal slot for mounting purposes.

Brass, nickel plated.

Specifications:

opecinedations.	
Insulation	PA
· Operating temperature:	
	(-40°F to +176°F)
• B4-E-M3-I	M3 external thread
• B4-E-M3.5-I	M3.5 external thread
• B4-E-M4-I	M4 external thread
• B4-F-M5-I	M5 external thread


Components:

• Insulators I-A2/4	#	24 5012
• B4-E-M3 adapter	#	23.5076
• B4-E-M3.5 adapter	#	23.5079
• B4-E-M4 adapter	#	23.5082
B4-F-M5 adapter	#	23.5085

⚠ Du

During installation, the terminal must be at zero potential.

Colors: 21 - 24



1:1

4 mm

Adapters

^p art No.	Туре			Nominal diameter	Withdraw. force	Rated current	Contact resistance
!3.1035 !3.5088	B4-E-IM4-I insulated B4-E-IM4 non-insulated	23		4 mm	-	25 A	-
!4.5012	I-A 2/4 insulator	5 7 9		Sockets 4 mm (.16 M 4 thread. Machir insulated or non-in	ied brass, nic	kel plated	. Available
		25		Operating temperat	ure:		40°C to +80°C 40°F to 176°F)
			1:1	Colors: 21, 22, 24,	29		
23.1036 23.5091	B4-E-IM5-I insulated B4-E-IM5 non-insulated I-KK 2/4 insulator	22		4 mm	-	25 A	
!4.5090	FRR 2/4 IIISUIAIOI	6 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8		Screw-on sockets 4 thread. Machined b insulated or non-in:	rass, nickel p	lated. Av	ailable
		24		Operating temperat	ure:		40°C to +80°C 40°F to 176°F)
			1:1	Colors: 21, 22, 24,	29		
6.9694	XWA-4/19	34.5	Multilarr" Equipped	4 mm	-	20 A	-
		87.8		Safety right-angled has a 4 mm plug ar angles in a fully ins designed to allow 9 there is restricted a	nd 4 mm soci ulated body. 10° entry to s	ket configi This adap	ured at right oter is
				Colors: 21 - 27, 29	1		
		ø4 ø5.1 ø6.2					
	HER	I	1:1				
36.9190	XWA-2/4	34.5	Muttilani" Equipped	4 mm 2 mm	-	10 A	-
		8.5		Safety right-angled has a 4 mm plug ar angles in a fully ins designed to allow 9 there is restricted a	nd 2 mm socl ulated body. 0° entry to sa	ket configu This adap	ured at right oter is
				Colors: 21 - 23			
	Hele	ø2.9 ø5.1	1:1				
			•				