



Weight: 17.54 g

Washer

Insulator

Body
Coupling Nut

Suitable Cables: RG58, JBY195, RG55, RG142, RG400, RG142-E, RG223

Tin-Zinc-Copper-Alloy 100 Over Copper 50

Tin-Zinc-Copper-Alloy 100 Over Copper 50

Tin-Zinc-Copper-Alloy 100 Over Copper 50

This part number complies with RoHS.

**Brass** 

Teflon Brass

**Brass** 

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



## CABLE ASSEMBLY INSTRUCTION TNC3200B-0058 JYE BAO CO., LTD. В С Α D Ε F G **BODY** GASKET WASHER CONTACT PIN WASHER **BRAID CLAMP** DIAGRAM ASSEMBLY INSTRUCTION 8.1 [.319] Step 1: STRIP AS SHOWN. 6 2.1 [.236] [.083] Step 2: SLIDE BRAID CLAMP " D " ,GASKET " E " , WASHER " F " AND NUT " G" OVER CABLE . Step 3: WRAP THE BRAIDING OVER " D ". Step 4: STRIP AS SHOWN. Step 5: SLIDE PREPARED CABLE INTO WASHER " C " . Step 6: PUT CONTACT PIN " B " ON CENTER CONDUCTOR AND SOLDER IN "Y". Step 7: FINALLY SCREW " G " ON THE CONNECTOR BODY " A ". FEDC B

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.