



Parts	Material	Plating (Micro-inch)
Cover	Brass	Gold 5 Over Nickel 50 Over Copper 50
Ferrule	Brass	Gold 5 Over Nickel 50 Over Copper 50
Retainer Ring	Beryllium Copper	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Contact Pin	Beryllium Copper	Gold 20 Over Nickel 50 Over Copper 50
Insulator	Teflon	
Body	Brass	Gold 5 Over Nickel 50 Over Copper 50
Barrel	Brass	Gold 5 Over Nickel 50 Over Copper 50
Coupling Nut	Brass	Gold 5 Over Nickel 50 Over Copper 50

Weight: 2.92 g

Suitable Cables: RG178, RG196, RG178-FEP

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION SMB3100A-9178 JYE BAO CO., LTD. Α В FERRULE BODY COVER ASSEMBLY INSTRUCTION DIAGRAM Step 1: STRIP AS SHOWN. Step 2: SLIDE FERRULE "A" OVER CABLE. Step 3: WRAP THE BRAIDING UPWARDS. Step 4: SLIDE CENTER CONDUCTOR ON THE CONTACT PIN OF CONNECTOR contact pin "B" AND SOLDER IN "Y". В Step 5: SLIDE FERRULE "A" TOWARDS THE CONNECTOR "B" AND CRIMP. **FORCE** Step 6: PRESS ON THE TOP OF "C" WITH JIGS AS JIG SHOWN.

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.