





Parts	Material	Plating(Micro-inch)
Ferrule	Brass	Tin-Zinc-Copper-Alloy 100 over Copper 50
Contact Pin	Brass	Gold 3 Over Nickel 50 Over Copper 50
Insulator	Teflon	
Body	Brass	Tin-Zinc-Copper-Alloy 100 over Copper 50

Weight: 7.0 g

Suitable Cables: RG58, JBY195

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION FME3100-0058 JYE BAO CO., LTD. Α В С BODY **CONTACT PIN FERRULE** DIAGRAM ASSEMBLY INSTRUCTION Step 1: STRIP AS SHOWN. 5.9 [.232] 3.9 [,154] Step 2: SLIDE FERRULE " C " OVER CABLE. Step 3: PUT PIN " B " ON CENTER CONDUCTOR AND CRIMP IN " Y ". С Step 4: LOOSEN BRAIDING AND SLIDE CONNECTOR " A " $\operatorname{\mathsf{IN}}$ PLACE. С Step 5: SLIDE FERRULE " C " TOWARDS THE CONNECTOR " A " AND CRIMP.

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.